

ASS. REC. BY:

REF:

C12/21007762/Kgc

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s KGC  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. SNM21D203950/C02  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SGY 6886G Yr Regn: 03, 20  
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or As  
 Make: BMW 520i c.c. 1998  
 Colour: M.P. white A/C: Insured / Std / NI / NA  
 Sp. Reading: 15697 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WBAJR12010CD55352  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: NI / S/Rim / STD / A/Rim or \_\_\_\_\_

Tyre Size: F: \_\_\_\_\_ R: 245/45R18

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU PIR SUMI / TOYO / YOKO or \_\_\_\_\_

Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 8 mm R/Bal. 7 mm  
 L/Bal. 8 mm L/Bal. 7 mm  
 D.O.A. 12/7/21 D.O.I. 6/8/2021  
 Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or C/S/R

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time       | Action / Instruction                              |
|-------------------|---|
| 10/08/21 @ 3.27pm | revised to Irene Tay via Merimen.                 |
|                   | Kenneth confirmed LS \$4550. (Red \$6727.04. 60%) |
|                   |   |
|                   |   |
|                   |   |

Date/Time, File Pass to?

: Prell. Report

1) 18/08 Typist

: Final Report

Date/Time, File Return to?

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S - RS \$

Fines

Others

TOTAL

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Report Format: MER-JP

Lump Sum H.B.k (\$) 4550



# KGC WORKSHOP PTE LTD

Since 1967

Sincere • Secure • Satisfaction



14 Ang Mo Kio St.63, Block B (S) 569116  
Tel : 6453 6279 / 6456 5410  
Email : contact@kgcworkshop.com.sg

*Not Withheld  
Penny After Paint  
3 days*

Goh Keng Leong  
14 Ang Mo Kio St 63  
Block B  
Singapore 569116

TP  
Date 16/7/2021  
No of Page : 1/2

Registraion No : SGY 6886G  
Accident Date : 12-Jul-21  
Our Ref : TP

Model : BMW 520I  
Chassis No: WBAJR12010CD55352  
Engine Capacity :

| S/No                         | Qty | Items                                 | Unit Price  | Amount          |
|------------------------------|-----|---------------------------------------|-------------|-----------------|
| 1                            | 1   | Front Bumper                          | \$ 1,384.80 | \$ 1,384.80 X   |
| 2                            | 1   | Front bumper retainer RHS             | \$ 36.80    | \$ 36.80 X      |
| 3                            | 1   | Front Bumper Lower Grille RHS         | \$ 117.00   | \$ 117.00 X     |
| 4                            | 1   | Front bumper Lower Grille (outer) RHS | \$ 69.00    | \$ 69.00 X      |
| 5                            | 1   | Front Fog Lamp Cover                  | \$ 80.00    | \$ 80.00 X      |
| 6                            | 1   | Front Fender RHS                      | \$ 938.00   | \$ 938.00 X     |
| 7                            | 1   | Headlamp Assy RHS                     | \$ 4,887.60 | \$ 4,887.60     |
| 8                            | 2   | Front parking sensor x2 (RHS)         | \$ 205.00   | \$ 410.00 X     |
|                              |     |                                       | \$          | 7,923.20        |
|                              |     |                                       | -5%         | \$ 396.16       |
| <b>Total for spare parts</b> |     |                                       | \$          | <b>7,527.04</b> |

### Special Nett

|                              |       |                    |          |                 |
|------------------------------|-------|--------------------|----------|-----------------|
| 1                            | 1 set | Front Bumper Clips | \$ 50.00 | \$ 50.00 X      |
| <b>Total for SP</b>          |       |                    | \$       | <b>50.00</b>    |
| <b>Sub-Total for Parts :</b> |       |                    | \$       | <b>7,577.04</b> |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



| S/No | Qty | Items   | Unit Price            | Amount                            |
|------|-----|---|-----------------------|-----------------------------------|
| 1    |     | To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mention repair parts, inclusive of replacement parts. |                       | 800.00 <i>200/</i>                |
| 2    |     | To putty and spray paint on all accident damage parts and other accident affected areas   |                       | 800.00 <i>440/</i>                |
| 3    |     | To perform paint protection film(ONERPRO) over the bumper and fender  |                       | ( <i>Bill</i> ) 1,800.00 <i>7</i> |
| 4    |     | To remove and refit reverse sensor & conduct distance safety setting  |                       | <i>na</i> 100.00 <i>X</i>         |
| 5    |     | To check wiring system to facilitate repair and refit the same  |                       | 100.00 <i>20/</i>                 |
| 6    |     | Apply rust proofing on the adjacent panels  |                       | <i>na</i> 100.00 <i>X</i>         |
|      |     |   | <b>TOTAL AMOUNT :</b> | <u>3,700.00</u>                   |
|      |     |   | <b>OVERALL COST :</b> | <u>11,277.04</u>                  |

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 16/07/2021 13:54 (SGT)  
Date of Accident ..... 12/07/2021 19:01 (SGT)  
Exact Location of Accident ..... 104 Towner Rd, Singapore 327827  
Additional Location Information ..... CARPARK  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SGY6886G  
  
INSURED/POLICYHOLDER  
  
Is company? ..... No  
Name Of Registered Owner ..... GOH KENG LEONG  
NRIC No ..... SXXXX806F  
Email Address ..... GOHKL@GMAIL.COM  
Mobile Phone No ..... (Phone) +65-97645177  
Alternative Phone No ..... +65-97645177

## VEHICLE PARTICULARS

Manufacturer ..... BMW  
Model ..... 520i  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1998

## INSURANCE COMPANY


Name of Insurance Company ..... Direct Asia Insurance (Singapore) Pte Ltd  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... MT/00894885  
Cover Note Number ..... 19/03/2021 - 18/03/2022

## DRIVER

Name of Driver ..... GOH KENG LEONG  
NRIC No ..... SXXXX806F

Date of accident: 12/7/2021 Time: 1901 Location: Car park of BLK 104 Tower Road  
My Vehicle A: SGX 6886 G Vehicle B: SKC 8913S Vehicle C: \_\_\_\_\_

SKETCH PLAN



A: SGX 6886 G  
B: SKC 8913S

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 12/7/2021 at about 1900 hours, the weather condition is raining. My car was parked along the car park of BLK 104 Tower Road. Car P collided into my car front right position as per my in car camera. I manage to find Car B and left a Note on the car, however Car B driver still yet to contact me till today.

Claim OD/TP at Ah Lim Motor  Claim OD/TP at other workshop  Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop : peh keng ty workshop (on sg)  
Email address : 091110@gmail.com  
& myself :  
Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)

[Signature]  
Reporting Officer's Signature  
Name:  
[Stamp]

RECEIVED 16 JUL 2021

COMPLETED 16 JUL 2021