

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21007765/KTCE2

Date: 15/12/2021

REFERENCE

Insured/Claimant: Lentor Ambulance Pte Ltd Policy No: DMCVSNW00105202002

Date of Loss: 13/07/2021

Nature of Claim: OD

Claim No: SNM21D203900/C01/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG894X**

Make & Model: MERCEDES-BENZ SPRINTER, 2.1 D 316 CDI (W906) (M)

Engine No: 65195534716554

Reg. Date: 03/12/2018 (Man. Year: 2018)

Chassis No: WDB9066332P628123

Colour: White

Odometer: 77896 km

Engine Capacity: 2143 cc

Market Value/New Car Price: S\$75,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/65R16

Rear Tyre Size: 235/65R16

Front Left Side: Continental 3 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Continental 8 mm

Rear Right Side: Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	200.00	0.00	200.00	100.00
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	200.00	0.00	200.00	100.00
- Excess (S\$)	0.00	1,250.00	-1,250.00	
(S\$)	200.00	-1,250.00	1,450.00	725.00
+ GST 7.00/0.00% (S\$)	14.00	0.00	14.00	100.00
Nett Amount (S\$)	214.00	-1,250.00	1,464.00	684.11

INSPECTION

Date of Assignment: 19/07/2021 Present Location:

S & H Motor Pte Ltd (Sin Ming)

Date Inspected: 21/07/2021 Inspected At:

S & H Motor Pte Ltd (Sin Ming)

160 Sin Ming Drive #07-02, Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Remaining Value :	\$75,000.00
OMV :	\$94,859.00
PARF Rebate (1) :	\$0.00
Quota Premium Paid :	\$0.00
COE Rebate (2) :	\$0.00
Total Rebate (1) + (2) = :	\$0.00

The total amount incurred will be Remaining Value \$75,000.00 minus Total Rebate \$0.00 = \$0.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 15 Dec 2021)

Parts: N/A MERCEDES-BENZ SPRINTER 2.1 D 316 CDI (W906) (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMG894X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<hr/>				
Miscellaneous Items				
1	1	Towing charges (winch out)	200.00	0.00
			<hr/>	
			Sub Total (\$\$)	200.00
			<hr/>	0.00

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >