



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL  
(BUDGET DIRECT INSURANCE)190  
CLEMENCEAU AVE #03-01 SINGAPORE SHOPPING  
CTR S239924

INV No. AC1807969  
INV Date 02/08/2018  
Reference CS3/AGI18013456/T1z4d3s  
Code AGI



### PROFESSIONAL SERVICE FEE

Vehicle No. FU 353A  
Insured Veh. SKA 8213P  
Claim No. C10001787/JM  
Policy No.  
Accident Date 17/07/2018  
Inspection Date 25/07/2018

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
<b>Subtotal</b>	<b>100.00</b>
<b>GST (7%)</b>	<b>7.00</b>
<b>Grand Total</b>	<b>107.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to

**'LKK Auto Consultants Pte Ltd'**

Date:	6/8/18
Claim Ref:	C10001787
Box ID:	8
Envelop ID:	006

LKK Auto Consultants Pte Ltd

*NSA*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AUTO & GENERAL INSURANCE (S) PL		Ref: CS3/AGI18013456/T1z4d3s2		
(BUDGET DIRECT INSURANCE)190 CLEMENCEAU AVE #03-01SINGAPORE SHOPPING CTR S239924		Date: 02-08-2018		
Code: AGI				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SKA 8213P	Veh. Inspected	FU 353A	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10001787/JM	Excess (\$)	0.00	
Assign From	JULIE MANGUBAT	Assign Date	24/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	DEUS	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	TA2000003667	Colour	BRONZE	
Odometer	46258 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	90/90 R17	PIRELLI	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	130/90 R15	PIRELLI	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.				
5. General Information				
Accident Date	17/07/2018	Inspect Date / Time	25/07/2018 ( 02:37 PM )	
Survey held at	CHEK KONG MOTOR 387B YEOW YEE INDUSTRIAL ESTATE WOODLANDS ROAD SINGAPORE 677948			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	

Report Ref No. CS3/AGI18013456/T1z4d3s2

### Inspected By



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEE,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. FU 353A

## INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

