

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM21007771/Bpa3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	09/05/2022	
	ATTN:KITTY			Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SH 8269Y	Veh. Inspected	k	SJU 525Z	
	Policy No.	P2419138	Coverage (\$)		0.00	
	Claim No.	S1M03DFQ	Excess (\$)		0.00	
	Assign From		Assign Date		19/07/2021	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA FIT 1.3G	c.c		1339	
	Engine No.	HIDDEN	Year of Reg.		2008	
	Chassis No.	GE61142710	Colour		RED	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/60 R15	HANKOOK		4 mm	
	L/H Front Tyre	185/60 R15	HANKOOK		4 mm	
	R/H Rear Tyre	185/60 R15	HANKOOK		4 mm	
	L/H Rear Tyre	185/60 R15	HANKOOK		4 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	09/07/2021	Inspection Dat	te	23/07/2021	
	Survey held at	BIFROST AUTO PTE LTD				
		8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days					