



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21007776/Kqf3n2 Date: 22/12/2021	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
<b>Insured Veh.</b>	SBA 73K	<b>Veh. Inspected</b>	SLR 8745U	
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00	
<b>Claim No.</b>	C10010806/CD	<b>Excess (\$)</b>	0.00	
<b>Assign From</b>	IVY RATILLA	<b>Assign Date</b>	21/07/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
<b>Make &amp; Model</b>	SUBARU FORESTER XT (A)	<b>c.c</b>	1998	
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017	
<b>Chassis No.</b>	JF1SJGK85JG097810	<b>Colour</b>	METALLIC DARK GREY	
<b>Odometer</b>	59445 KM	<b>Steering</b>	IN ORDER	
<b>Brakes</b>	IN ORDER	<b>Modification</b>	STANDARD ALLOY RIM	
<b>General</b>	GOOD			
<b>3. Conditions of Tyres</b>				
	<b>Size</b>	<b>Make</b>	<b>Balance</b>	
<b>R/H Front Tyre</b>	225/55 R18	YOKOHAMA	8 mm	
<b>L/H Front Tyre</b>	225/55 R18	YOKOHAMA	8 mm	
<b>R/H Rear Tyre</b>	225/55 R18	YOKOHAMA	8 mm	
<b>L/H Rear Tyre</b>	225/55 R18	YOKOHAMA	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
<b>Accident Date</b>	07/07/2021	<b>Inspection Date</b>	22/07/2021	
<b>Survey held at</b>	BH AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>			<b>4 Working Days</b>	