

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/196R GS1 Reg. No. 19-900/196-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL		Ref:	CS/AGI21007793/Kqf3e2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE		Date:	22/11/2021	
				Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJT 9363U	Veh. Inspected		SCM 4515B	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10010944/CD	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		21/07/2021	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ E250 CGI (A)	c.c		1796	
	Engine No.	HIDDEN	Year of Reg.		2010	
	Chassis No.	WDD2120472A281073	Colour		METALLIC SILVER	
	Odometer	104134 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/55 R16	MICHELIN		7 mm	
	L/H Front Tyre	225/55 R16	MICHELIN		7 mm	
	R/H Rear Tyre	225/55 R16	MICHELIN		7 mm	
	L/H Rear Tyre	225/55 R16	MICHELIN		7 mm	
4.	I. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	16/07/2021	Inspection Date)	21/07/2021	
	Survey held at	Survey held at THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

7 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: