

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SMRT AUTOMOTIV	VE SERVICES PTE LTD		Ref:	CS3/SMR21007795/T1uf3e2	
	60 WOODLANDS I E4SINGAPORE 75	NDUSTRIAL PARK 7705		Date:	02/08/2021	
				Code:	SMR	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SG 5158J	Veh. Inspected	t	SJF 23J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	BUS/07/21/5030	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		21/07/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	B.M.W. M3 COUPE	c.c		3999	
	Engine No.	HIDDEN	Year of Reg.		2012	
	Chassis No.	WBSKG92080E997685	Colour		BLUE	
	Odometer	93649 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	285/30 R20	MICHELIN		6 mm	
	L/H Front Tyre	285/30 R20	MICHELIN		6 mm	
	R/H Rear Tyre	285/30 R20	MICHELIN		6 mm	
	L/H Rear Tyre	285/30 R20	MICHELIN		6 mm	
4.	1. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.					
5.	General Information					
	Accident Date	17/07/2021	Inspect Date /	Time	21/07/2021 (01:37 PM)	
	Survey held at	2 Kaki Bukit Ave 2 #01-33				
	Repairer	AUTO ASSIST SG				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$8,000					
5b. Estimate Days of Repair						
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		9 Worki	ing Days	

Report Ref No. CS3/SMR21007795/T1uf3e2

Inspected By

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.