

ASS. REC. BY:

Stere

REPT

CS/ AIG 21007796 / ETF 3

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

at

Insured:

Policy No. 1900114470

Claims No. 2011287764SG

Sum Insured:

Excess:


S\$0.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Vol.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SDH 9923M

Yr Regn:

28/6/19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Tractor or

Make:

KIA Cerato

c.c

1591

Colour:

Red

A/C:

Insured / Std / N / W

Sp. Reading

16560

T/Radio:

Insured / Std / N / W

Eng/No:

C/No:

KNAF 3416 N.K. 5049704

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Mod: Nil / S / Film / STD A/R / or

Tyre Size:

P:

225/45R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

U/Bal.

4

mm

U/Bal.

4

mm

D.O.A.

21/7/21

D.O.A.

21/7/21

Survey held at

Cycle / collapse

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV-79K

Part by part \$6072.40, 7days  
red: 6113.20:50%

File/Time, File, Pass 107



: Prel. Report



: Final Report

File/Time, File Return 107

Days Of Repair:

7

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS + SI

Phone

Others

TOTAL

Add Fee:



: Site Insp

(\$



: Interview

(\$



: Tech. Inve

(\$



: Weigh and

(\$

Approved/Initial:

Date/Time/Initial:



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



### ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
ATG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 ATG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /EUGENE SEAH WEE JIN (EUGENE SHE Reg No/Reg Date SDH9923M*KC17/ 28/06/201 Date In/Mileage / 16560 Chassis No KNAF3416MK5049704 Engine No G4FGKH744163 Make/Model KIA/CERATO 1.6 A SX SR G518 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	21/07/2021/ 10:50	BLE	261 / Edwin Caina	36434			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2400.00
RENEW RR BUMPER , BOOTLID & RR END PNL					3.5 X 420			1410
REPAIR RR FLR PNL , LHR FENDER & RHR FENDER								
E PNT98000								2100.00
RESPRAY RR BUMPER , RR END PNL , BOOTLID , RR FLR PNL , LHR FENDER & RHR FENDER					3 X 48"(CR5)			1440
E PNT88000								120.00
REMOVE & REFIT BOOTLID COMPONENT								
E PNT88000								120.00
REMOVE & REFIT RR FLR BOARD , TRIM & CARPET					(photo)			
A 54900099								30.00
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								50.00
SUPPLY RR NUMBER PLATE WITH CASING								
E PNT88000								80.00
REMOVE & REFIT REVERSE SENSOR								
M SUNDRY								40.00
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								40.00
SUPPLY BODY PNL SEALANT								
M SUNDRY								40.00
SUPPLY C&C BADGE								
M SUNDRY								20.00
Sundries								
M COVER-RR BUMPER					1.00	651.00	20.00	520.80
M COVER-RR BUMPER LWR					1.00	241.00	20.00	192.80
M COVER-RR BUMPER UNDER,LH					1.00	33.00	20.00	26.40
M COVER-RR BUMPER FOG LAMP,LH					1.00	88.00	20.00	70.40
M COVER-RR BUMPER FOG LAMP,RH					1.00	88.00	20.00	70.40
M LAMP ASSY-SIDE T/SIGNAL,LH					1.00	181.00	20.00	144.80
M LAMP ASSY-SIDE T/SIGNAL,RH					1.00	181.00	20.00	144.80

Confirm &amp; accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewal the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



### ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /EUGENE SEAH WEE JIN (EUGENE SHE) Reg No/Reg Date SDH9923M*KC17/ 28/06/201 Date In/Mileage / 16560 Chassis No KNAF3416MK5049704 Engine No G4FGKH744163 Make/Model KIA/CERATO 1.6 A SX SR G518 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	21/07/2021/ 10:50	BLE	261 / Edwin Caina	36434
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	EXTN WIRING ASSY-BWS	1.00	207.00	20.00	165.60
M	BEAM-RR BUMPER	1.00	318.00	20.00	254.40
M	STAY-RR BUMPER LH	1.00	65.00	20.00	52.00
M	STAY-RR BUMPER RH	1.00	65.00	20.00	52.00
M	BRACKET-RR BEAM UPR MTG, LH	1.00	9.00	20.00	7.20
M	BRACKET-RR BEAM UPR MTG, RH	1.00	9.00	20.00	7.20
M	BRACKET-RR BEAM LWR, CTR	1.00	6.00	20.00	4.80
M	BRACKET-RR BEAM LWR MTG	1.00	6.00	20.00	4.80
M	ANTENNA ASSY-SMARTKEY	1.00	46.00	20.00	36.80
M	COVER-RR BUMPER UNDER, RH	1.00	33.00	20.00	26.40
M	BRACKET ASSY-RR BPR SIDE UPR	1.00	25.00	20.00	20.00
M	BRACKET-ASSY RR BPR SIDE UPR, R	1.00	31.00	20.00	24.80
M	ULTRASONIC SENSOR ASSY-BWS	4.00	163.00	20.00	521.60
M	CLIP	10.00	1.00	20.00	8.00
M	PANEL ASSY-TRUNK LID	1.00	1297.00	20.00	1037.60
M	HINGE ASSY-TRUNK LID, LH	1.00	97.00	20.00	77.60
M	HINGE ASSY-TRUNK LID, RH	1.00	97.00	20.00	77.60
M	PANEL ASSY-BACK	1.00	324.00	20.00	259.20
M	TRIM ASSY-RR TRANSVERSE	1.00	41.00	20.00	32.80
M	MAT ASSY-LUGGAGE COVERING	1.00	211.00	20.00	168.80
M	W/STRIP-TRUNK LID OPNG	1.00	100.00	20.00	80.00
M	LATCH ASSY-TRUNK LID	1.00	112.00	20.00	89.60
M	STRIKER ASSY-TRUNK LID	1.00	40.00	20.00	32.00
M	TRIM ASSY-TRUNK LID	1.00	202.00	20.00	161.60
M	LOGO ASSY-KIA SUB	1.00	32.00	20.00	25.60
M	EMBLEM-CERATO	1.00	28.00	20.00	22.40
M	LAMP ASSY-REAR COMB INSIDE, LH	1.00	608.00	20.00	486.40
M	LAMP ASSY-REAR COMB INSIDE, RH	1.00	608.00	20.00	486.40
M	LAMP ASSY-REAR COMB OUTSIDE, LH	1.00	675.00	20.00	540.00
M	LAMP ASSY-REAR COMB OUTSIDE, RH	1.00	675.00	20.00	540.00
M	LAMP ASSY-CENTER GARNISH	1.00	690.00	20.00	552.00

Confirm &amp; accepted by

SURVEYOR NAME: Steve CLKK 21/7/21, 12:00pm

SURVEYOR SIGNATURE: [Signature]

7% GST on

Nett 12185.60

12,185.60

DATE: EXCERS - 1, P/P, P/L

Total Payable

13,038.59

Authorized signatory and company stamp

7 dgs

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.