



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /EUGENE SEAH WEE JIN (EUGENE SHE Reg No/Reg Date SDH9923M*KC17/ 28/06/201 Date In/Mileage / 16560 Chassis No KNAF3416MK5049704 Engine No G4FGKH744163 Make/Model KIA/CERATO 1.6 A SX SR G518 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	21/07/2021/ 10:50	BLE	261 / Edwin Caina	36434			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER , BOOTLID & RR END PNL REPAIR RR FLR PNL , LHR FENDER & RHR FENDER					3.5 X 400			1493 2400.00
E PNT98000 RESPRAY RR BUMPER , RR END PNL , BOOTLID , RR FLR PNL , LHR FENDER & RHR FENDER					3 X 480(CRS)			1443 2100.00
E PNT88000 REMOVE & REFIT BOOTLID COMPONENT								120.00
E PNT88000 REMOVE & REFIT RR FLR BOARD , TRIM & CARPET					(photo)			120.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								120.00
M SUNDRY SUPPLY RR NUMBER PLATE WITH CASING								X 50.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR								80.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS								40.00
M SUNDRY SUPPLY BODY PNL SEALANT								40.00
M SUNDRY SUPPLY C&C BADGE								40.00
M SUNDRY Sundries								20.00
M COVER-RR BUMPER					1.00	651.00	20.00	520.80
M COVER-RR BUMPER LWR					1.00	241.00	20.00	192.80
M COVER-RR BUMPER UNDER, LH					1.00	33.00	20.00	26.40
M COVER-RR BUMPER FOG LAMP, LH					1.00	88.00	20.00	70.40
M COVER-RR BUMPER FOG LAMP, RH					1.00	88.00	20.00	70.40
M LAMP ASSY-SIDE T/SIGNAL, LH					1.00	181.00	20.00	144.80
M LAMP ASSY-SIDE T/SIGNAL, RH					1.00	181.00	20.00	144.80

Confirm & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs of replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /EUGENE SEAH WEE JIN (EUGENE SHE) Reg No/Reg Date SDH9923M*KC17/ 28/06/201 Date In/Mileage / 16560 Chassis No KNAF3416MK5049704 Engine No G4FGKH744163 Make/Model KIA/CERATO 1.6 A SX SR G518 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	21/07/2021/ 10:50	BLE	261 / Edwin Caina	36434
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M EXTN WIRING ASSY-BWS	?	1.00	207.00	20.00	165.60
M BEAM-RR BUMPER	BB (photo)	1.00	318.00	20.00	254.40
M STAY-RR BUMPER LH	BT	1.00	65.00	20.00	52.00
M STAY-RR BUMPER RH	BT	1.00	65.00	20.00	52.00
M BRACKET-RR BEAM UPR MTG, LH	?	1.00	9.00	20.00	7.20
M BRACKET-RR BEAM UPR MTG, RH	?	1.00	9.00	20.00	7.20
M BRACKET-RR BEAM LWR, CTR	CRU	1.00	6.00	20.00	4.80
M BRACKET-RR BEAM LWR MTG	CRU	2.00	6.00	20.00	4.80
M ANTENNA ASSY-SMARTKEY	?	1.00	46.00	20.00	36.80
M COVER-RR BUMPER UNDER, RH	?	1.00	33.00	20.00	26.40
M BRACKET ASSY-RR BPR SIDE UPR, L	?	1.00	25.00	20.00	20.00
M BRACKET-ASSY RR BPR SIDE UPR, R	?	1.00	31.00	20.00	24.80
M ULTRASONIC SENSOR ASSY-BWS	?	4.00	163.00	20.00	521.60
M CLIP	NEC	10.00	1.00	20.00	8.00
M PANEL ASSY-TRUNK LID	BB	1.00	1297.00	20.00	1037.60
M HINGE ASSY-TRUNK LID, LH	?	1.00	97.00	20.00	77.60
M HINGE ASSY-TRUNK LID, RH	?	1.00	97.00	20.00	77.60
M PANEL ASSY-BACK	BB (photo)	1.00	324.00	20.00	259.20
M TRIM ASSY-RR TRANSVERSE	?	1.00	41.00	20.00	32.80
M MAT ASSY-LUGGAGE COVERING	?	1.00	211.00	20.00	168.80
M W/STRIP-TRUNK LID OPNG	CRU	1.00	100.00	20.00	80.00
M LATCH ASSY-TRUNK LID	?	1.00	112.00	20.00	89.60
M STRIKER ASSY-TRUNK LID	?	1.00	40.00	20.00	32.00
M TRIM ASSY-TRUNK LID	?	1.00	202.00	20.00	161.60
M LOGO ASSY-KIA SUB	NEC	1.00	32.00	20.00	25.60
M EMBLEM-CERATO	NEC	1.00	28.00	20.00	22.40
M LAMP ASSY-REAR COMB INSIDE, LH	?	1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB INSIDE, RH	?	1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB OUTSIDE, LH	?	1.00	675.00	20.00	540.00
M LAMP ASSY-REAR COMB OUTSIDE, RH	?	1.00	675.00	20.00	540.00
M LAMP ASSY-CENTER GARNISH	?	1.00	690.00	20.00	552.00

Confirm & accepted by

SURVEYOR NAME: Steve CLKK 21/7/21, 12:10pmSURVEYOR SIGNATURE: DD-MY ALDATE: Excurs - ?, P/P, P/L sy

Nett 12,185.60
7% GST on 12185.60 852.99

Total Payable 13,038.59

Authorized signatory and stamp

7 dgs

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.