

速 良 摩 哆 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT

1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883

Tel: 6747 7858, 6747 2343 Fax: 6742 0012

E-mail: slmoi@singnet.com.sg

Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒杆噴漆
代理保險：車禍
賠償及買賣汽車

MR LIM BOON HOCK

DATE: 19/07/2021

DOA : 15/07/2021

ESTIMATE REPAIR FOR VEHICLE NO. SLA 9893 H (AUDI A4)

	Description	List Price
1 pc	Front bumper <i>Deep cut</i>	\$ 2,111.00 ✓
1 pc	Front bumper side retainer (rh) <i>1.1</i>	\$ 35.90 X
1 pc	Front sport rim <i>2</i>	\$ 990.00 X
		\$ 3,136.90
	Less : 10%	\$ (313.69)
		\$ 2,823.21
	<u>Special Nett Items</u>	
	Labour charges for knocking & replacing parts.	\$ 300.00 <i>200</i>
	Spraypainting	\$ 600.00 <i>500</i>
	TOTAL : *	\$ 3,723.21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not defined
LKK
2/5 # 2050/
2 days.
21/7/21
Weight. other repair.

LKK Cecilia