



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 756 Y**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORAGNIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	800
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER AND BOTH FRONT WHEEL ARCH TRIMS. <i>300x2=600</i>	\$ 3,000.00	<del>800</del> 1400
5	TO SUPPLY FILM AND RE-WRAP RADIATOR GRILLE	TBC	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 5,152.00</b>	