

TPECKS.
Denise.

SLN2974K. 2011 June
BMW 640i 2979cc
WBA LW72080CS826S3

Rear Number Plate	cracked	50(SN) ✓
Rear Number Plate Holder.	Deformed	30(SN) ✓
Rear Bumper	Deformed	2088 ✓
Rear Bumper Clips.	None	50(SN) ✓
Rear Bumper Side Holder.	X02 None	$125 \times 2 = 250$ ✓
Rear Bumper Inner Guide (Centre).	Cracked	161 ✓
Rear Bumper Reinforcement.	X4 None	751 X
Rear Bumper UnderCover	Cracked	145 ✓
Rear Bumper UnderCover Clips.	None	20(SN) ✓
Reverse Sensor	X02 Damaged	$280 \times 2 = 560$ ✓
Rear End Panel.	Reps	885 X.
Rear End Panel Top Garnish.	cracked	212 ✓

SLN2974K.

Taillamp x 02

Bootlid Lock

Bootlid Weatherstripe.

2
xap
wch

705 x 2 = 1410 x

485 x

245. x

Panel Beating.

Spray Painting.

Wiring.

To remove reverse sensor

To spray tuff coat.

To remove upholstery.

~~800~~ 300.

~~800~~ 500.

~~100~~ 30

~~120~~ 60

~~150~~ 40

~~150~~ 40

Labour: 970

total: 4114.40.

2/s: 3.3K.

03 Days

hist: 3416.

ten 10%: 3074.40.

S.N: 70

9462

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: