

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21007809/UGS3Q2**Date:** 27/01/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070131952
Claimant Vehicle No :	SLC8364P	Insured Vehicle No :	GBH7266M
Date of Loss:	19/07/2021	Nature of Claim:	TP
		Claim No:	3229148234SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC8364P	Engine No:	G4FGGH613106
Make & Model:	KIA FORTE K3, 1.6 EX (A)	Chassis No:	KNAFX411MG5601919
Reg. Date:	27/05/2016 (Man. Year: 2016)	Odometer:	60985 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,521.00	3,454.40	11,066.60	76.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,770.00	1,600.00	2,170.00	57.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,291.00	5,054.40	13,236.60	72.37
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	18,291.00	4,000.00	14,291.00	78.13
+ GST 7.00/7.00% (S\$)	1,280.37	280.00	1,000.37	78.13
Nett Amount (S\$)	19,571.37	4,280.00	15,291.37	78.13
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,532.00		
Global Sum Settlement (S\$)		4,500.00		

INSPECTION

Date of Assignment:	21/07/2021		
Date Inspected:	21/07/2021	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Bent	1,145.00 F	*1,089.00 FL
2	1		*BOOTLID REAR LOGO	Necessary	85.00 F	*48.00 FL
3	2		*BOOTLID REFLECTORS	Not Necessary	810.00 F	*- FL
4	1		*BOOTLID FORTE EMBLEM	Necessary	82.00 F	*52.00 FL
5	1		*BOOTLID K3 EMBLEM	Necessary	60.00 F	*50.00 FL
6	1		*BOOTLID INNER LOCK	Serviceable	119.00 F	*- FL
7	1		*BOOTLID C&C LOGO	Necessary	60.00 F	*52.00 FL
8	2		*BOOTLID HINGES	Not Necessary	330.00 F	*- FL
9	1		*REAR BUMPER	Deformed	845.00 F	*831.00 FL
10	1		*REAR BUMPER LOWER	Deformed	1,800.00 F	*600.00 FL
11	1		*REAR BUMPER REFLECTOR N/S	Cracked	68.00 F	*68.00 FL
12	1		*REAR BUMPER REINFORCEMENT	Cracked	405.00 F	*391.00 FL
13	2		*REAR BUMPER REINFORCEMENT BRACKETS	Not Necessary	210.00 F	*- FL
14	3		*REAR BUMPER REINFORCEMENT LOWER BRACKETS	Not Necessary	75.00 F	*- FL
15	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
16	1		*REAR END PANEL	Repair	689.00 F	*- FL
17	1		*REAR END PANEL TOP GARNISH	Not Necessary	315.00 F	*- FL
18	1		*REAR FLOOR PANEL	Not Necessary	1,280.00 F	*- FL
19	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	405.00 F	*- FL
20	2		*REAR FENDERS	Repair	2,200.00 F	*- FL
21	2		*REAR FENDER INNER TRIMS	Not Necessary	798.00 F	*- FL
22	1		*TAILLAMPS	N/S Cracked	1,210.00 F	*385.00 FL
23	2		*TAILLAMP HOUSING PANEL	Not Necessary	970.00 F	*- FL
24	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
25	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*- FS
26	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,521.00	3,816.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	361.60
Total Parts (\$\$)	14,521.00	3,454.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	100.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY	New	120.00	80.00
5	TO SPRAY RUST PROOFING	New	100.00	40.00
6	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	550.00
7	TO PUTTY & SPRAY PAINTING	New	1,500.00	800.00
			Gross Labour Cost (\$\$)	3,770.00
				1,600.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >