

# PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE (510607)

BUSINESS REGN. No. 53193457L


Hp 96699986

## INVOICE

Mr. Zhang Wei  
C/o JD Motorsports Pte Ltd  
25 Kaki Bukit Road 4  
# 06-38 Synergy @ KB  
Singapore 417800

Invoice No : PA/20040007/tpw  
Our Ref : PA/SKG7258/0120/tpw  
Date : 03 April 2020

Claim Type	Third Party	Date of Accident	: 06 January 2020
Vehicle No.	SKG 7258 K	Date of Inspection	: 08 January 2020
No	Description		Amount (S\$)
1	Survey fees inclusive of Transportation and Photographs (38) copies		\$538.00
		Total	\$538.00
Singapore Dollar: Five Hundred And Thirty Eight Only			
All payments made payable to : Prudent Adjustors Services			

  
Prudent Adjustors Services

## PRUDENT ADJUSTORS SERVICES

BLOCK 607 ELIAS ROAD #05-192

SINGAPORE (510607)

BUSINESS REGN. No. 53193457L

Hp 96699986

### VEHICLE DAMAGE INSPECTION REPORT

Mr. Zhang Wei  
C/o JD Motorsports Pte Ltd  
25 Kaki Bukit Road 4  
# 06-38 Synergy @ KB  
Singapore 417800

Our Ref : PA/SKG7258/0120/tpw  
Date : 03 April 2020

#### REFERENCES

Claim Type	: Third Party	Date of Accident	: 06 January 2020
Vehicle No.	: SKG 7258 K	Date of Assignment	: 08 January 2020
Make	: Nissan	Date of Inspection	: 08 January 2020
Model	: Elgrand Highway Star 2.5 MCVT	Date of Re-inspn.	: 10 January 2020
Reg. Date	: 29 September 2012	Chassis No	: JN1TBAE52Z0800028
Color	: Black	Engine No	: Blocked
Odometer	: 282784km		

#### TYRE CONDITION

	<u>Front near side</u>	<u>Front off side</u>	<u>Rear near side</u>	<u>Rear off side</u>
Make	Pirelli	Pirelli	Pirelli	Pirelli
Size	235/55 R18	235/55 R18	235/55 R18	235/55 R18
Thread Balance	6 mm	6 mm	8 mm	8 mm

#### GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at rear portion  
Please refer to photographs and assessment of repairs for details  
Enclosed (38) photographs depicting damage

Original Quotation : \$4,157.48

Revised Assessment \$3,500.00 Lump sum

Survey conducted at JD Motorsports Pte Ltd

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately  
Seven (7) days to complete.

This survey was conducted on a "WITHOUT PREJUDICE" basis.

**Note:** The workshop has agreed to undertake the repair on a lump sum basis, and or the use of ex-stock  
Reconditioned parts whichever is possible

## **PRUDENT ADJUSTORS SERVICES**

Vehicle No: **SKG 7258 K**

Our Ref: PA/SKG7258/0120/tpw

### **ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS**

<u>S/N</u>	<u>Description</u>	<u>Qty</u>	<u>Condition</u>	<u>Original Quotation</u>	<u>Revised Quotation</u>
1	Rear bumper fascia	1 pc	Dented	1,272.80	1,272.80
2	Rear bumper reinforcement	1 pc	Dented	632.40	632.40
3	Rear bumper sponge	1 pc	Cracked	110.80	110.80
4	Rear bumper top stay @ \$70.40/-	4 pcs	Bent	281.60	281.60
5	Rear bumper bracket @ \$85.40/-	2 pcs	Bent	170.80	170.80
6	Rear bumper side retainer @ \$57/-	2 pcs	Necessary	114.00	114.00
7	Rear tail gate door	1 pc	Dented	2,923.50	2,923.50
8	Rear tail gate auto lock sensor actuator	1 pc	Malfunction	370.50	370.50
9	Rear end panel	1 pc	Repair	742.40	~
10	Rear end panel top garnish	1 pc	Deform	216.80	216.80
				6,835.60	6,093.20
List price less 30%				2,050.68	1,827.96
				4,784.92	4,265.24
<u>Nett item</u>					
11	Rear emblem "XTRONIC CVT"	1 pc	Necessary	61.50	61.50
12	Rear emblem "HIGHWAY"	1 pc	Necessary	68.60	68.60
13	Rear emblem "STAR"	1 pc	Necessary	63.70	63.70
14	Back door weather-strip	1 pc	Necessary	201.20	201.20
				395.00	395.00
less 10%				39.50	39.50
				355.50	355.50
<u>Special nett item</u>					
15	Rear bumper sensor	1 set	Malfunction	300.00	280.00
16	Rear bumper clip @ \$8/-	4 pcs	Necessary	32.00	32.00
17	Tailgate inner trim board clip	1set	Necessary	80.00	60.00
18	Tailgate windscreen sealant	2 tube	Necessary	160.00	120.00
19	Tailgate windscreen inner seal	1 pc	Necessary	186.00	186.00
20	Tailgate sealant	2 tube	Necessary	160.00	120.00
				918.00	798.00

## **PRUDENT ADJUSTORS SERVICES**

Vehicle No: **SKG 7258 K**

Our Ref: PA/SKG7258/0120/tpw

### **ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS**

#### **Labour**

Remove and install rear windscreen	200.00	150.00
Remove, repair & replacement of accident damaged parts	1,200.00	1,000.00
Tuff kote	100.00	80.00
Transfer tailgate component	120.00	80.00
To remove and refit reverse sensor.	120.00	80.00
Respray rear pumper tailgate, rear end panel	1,500.00	1,200.00
	<hr/>	<hr/>
	3,240.00	2,590.00
 Total parts & labour concluded	 9,298.42	 8,008.74
 Lump sum repair adjustment		 6,400.00

The information contained in this document is privileged and confidential and is intended for the exclusive use of the addressee designation. If you are not the addressee; any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this document not meant for you, please contact us immediately to arrange for it to return.

  
\_\_\_\_\_  
Prudent Adjustors Services  
Bok Jee Tan

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 854J

### Vehicle Details

Vehicle No.: SKG7258K

Vehicle to be Exported: Yes

Intended Deregistration Date: 30 Jan 2020

Vehicle Make: NISSAN

Vehicle Model: ELGRAND HIGHWAY STAR 2.5 MCVT  
8AB HID SR

Primary Colour: Black

Manufacturing Year: 2012

Engine No.: QR25957800Q

Chassis No.: JN1TBAE52Z0800028

Maximum Power Output: 125.0 kW (167 bhp)

Open Market Value: \$44,041.00

Original Registration Date: 29 Sep 2012

First Registration Date: 29 Sep 2012

Transfer Count: 1

Actual ARF Paid: \$44,041.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 28 Sep 2022

PARF Rebate Amount: \$26,424.00

### Intended COE Rebate Details

COE Expiry Date: 28 Sep 2022

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$84,389.00

COE Rebate Amount: \$22,479.00

**Total Rebate Amount: \$48,903.00**

The information contained herein is correct as at 30 Jan 2020

OK





















PRUDENT A.



PRUDENT ADJ











Re-Survey







PRUDENT ADVISORY



Re-Survey

PRUDENT ADVISORY







Re-Survey





PRUDENT ADJ.

Re-Survey

PRUDENT ADJ.