

(08/11/13) wef
ASS. BY: Marcus

REF: CC4/A1621007811/4953

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: FX 83834
at Workshop m/s 210 hr
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: \$2500
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT 758B

Veh No: FX 83834 Yr Regn: 27/8/12
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Yamaha FX16 C.C. 153
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading: Damaged T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: ME121C007C2008330
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 100-80-17
R: 130-70-17 PIR
BS / PUR / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOKO / YOKO or
Front 6 mm Rear 6 mm
R/Bal. mm R/Bal. mm
L/Bal. mm L/Bal. mm
D.O.A. 15/7/14 D.O.I. 21/7/14
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S R/L, N/S S/L
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____
Created 26-8-2022 MA 230
Not \$220
31/7/14 45 \$1000 confirmed with MR Teo.

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report
1) _____
Date/Time, File Return to? _____
2) _____

Days Of Repair: _____
Resurvey No. of Trip: _____ Survey Fee: _____
Transportation: _____
Add Fee: ☐ : Site Insp (\$)) S + RS, SI
☐ : Interview (\$)) Photos
☐ : Tech. Invs (\$)) Others
☐ : Weekend (\$))
TOTAL _____

Report Format :
Lump Sum / I.B.I: (\$))

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

ceci

4581000
3 days

Name : Lua Wei Ming

Accident Date : 15-Jul-21

Vehicle No : FX8383U

Vehicle Model : Yamaha FZ16

Accident Involving SMA8991C And FX8383U on 15 July 2021

Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
1	Front fender R X	\$ 105.00 X
2	Fork inner tubes S2 X	\$ 480.00 X
2	Fork outer tubes n/s Daged 1pc 220	\$ 500.00 1pc
1	Fork under bracket 11 X	\$ 265.00 X
1	Front rim shaft S2 42	\$ 55.00 ✓
1	Front rim bearing 11 X	\$ 45.00 X
1	Front brake disc 11 X	\$ 185.00 X
1	Headlamp 11 X	\$ 520.00 X
1	Handle-bar 11 X	\$ 150.00 X
1	Handle-bar balancer 11 X	\$ 68.00 X
1	Hand grip (1 set) 11 X	\$ 85.00 X
1	Front side lower cover one ✓	\$ 70.00 ✓
1	Clutch lever 11 X	\$ 35.00 X
2	Side board n/s cut 1pc 145	\$ 300.00 1pc
1	Side stand Daged	\$ 95.00 ✓
1	Main stand 11 X	\$ 135.00 X
2	Front footrest 11 X	\$ 96.00 X
2	Front footrest brackets 11 X	\$ 220.00 X
1	Gear pedal S2 ✓	\$ 58.00 ✓
2	Rear footrest S2 X	\$ 104.00 X
1	Engine cover one ✓	\$ 480.00 ✓
		\$ 4,051.00
	Less 10%	\$ 405.10
		\$ 3,645.90

Special Nett Items

1	Number plate (1 set) 11 X	\$ 38.00 X
2	Fork oils n/s 15	\$ 30.00 15
2	Fork oil seals n/s 20	\$ 56.00 20
1	Steering cone (1 set) n/s 60	\$ 95.00 60
1	Engine cover gasket n/s ✓	\$ 65.00 ✓
1	Engine oil n/s S2 17.50	\$ 35.00 17.50
		\$ 319.00

not Afford

21/7/21

3 days

2/581000

Whyphoo Aff. rep.

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : **Lua Wei Ming**

Accident Date : **15-Jul-21**

Vehicle No : **FX8383U**


Vehicle Model : **Yamaha FZ16**

Accident Involving SMA8991C And FX8383U on 15 July 2021

Estimated Repair Costs

<u>S/No.</u>	<u>Labour</u>		
1	To provide towing service (LOD)	\$	60.00 ✓
2	To check wiring and reset headlamp focusing	\$	17 80.00 X
3	To repair body frame	\$	17 380.00 X
4	To provide labour	\$	480.00 250
		\$	<u>1,000.00</u>
Grand Total		\$	<u>4,964.90</u>

Singapore Dollars: Four Thousand Nine Hundred Sixty-Four and Cents: Ninety only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-910
102
819
130650