

REF: Acm /

Not Noted
11 Lys @ 400dp
Presume Asa Pain



Teo Jit Heng
56 Jalan Keruing
Singapore 808976

File No: SH/2021/061/07/001/TP
Date: 05-July-2021

Estimated cost of repair for vehicle no: SJD4506S Nissan Presage
Accident involving vehicle no: SJD4506S & SJW19H on 03.07.2021

Description	Quantity	Cost Price
Front grille	1	S 485.30
Front grille clips (1 set)	1	S 22.00
Front bumper 646	1	S 710.60
Front bumper clips (1 set)	1	S 35.00
LH Front bumper retainer	1	S 35.00
Front bumper sponge	1	S 265.30
Front bumper reinforcement	1	S 540.60
LH Front bumper fog lamp chrome rim	1	S 85.20
LH head lamp inner panel	1	CM S 682.80
		S 2,861.80
	Less 30%	S 858.54
		S 2,003.26
RH head lamp 1343.30	1	Nett S 1,477.60
LH head lamp 1343.30	1	Nett S 1,477.60
Front grille emblem	1	Nett S 95.80
LH Front bumper fog lamp	1	Nett S 379.00
		S 3,430.00
	Less 10%	S 343.00
		S 3,087.00

To remove front damaged parts, to jack out front support panel, front body, and to straighten out front chassis, to reshape and repair LH front fender and inner panel, head lamp inner panel, front support panel, and adjust body panel alignment S 550.00 400

To spray paint affected front and inner damaged portion inclusive of preparatory works and material S 580.00 400

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp S 25.00 20

S 6,245.26

T/Party: Sompo Insurance Singapore Pte. Ltd.

Teo Jit Heng
56 Jalan Keruing
Singapore 808976

Not Notarized
61 days @ 400dp
Presage After Pain
4 days



File No: SH/2021/061/07/001/TP
Date: 05-July-2021

Estimated cost of repair for vehicle no: **SJD4506S** Nissan Presage
Accident involving vehicle no: **SJD4506S** & **SJW19H** on **03.07.2021**

Description	Quantity	Cost Price
Front grille	1	S <i>MBUM</i> 485.30 <i>✓</i>
Front grille clips (1 set)	1	S <i>MB</i> 22.00 <i>✓</i>
Front bumper <i>646</i>	1	S <i>CM</i> 710.60 <i>✓</i>
Front bumper clips (1 set)	1	S <i>MB</i> 35.00 <i>✓</i>
LH Front bumper retainer	1	S <i>MB</i> 35.00 <i>X</i>
Front bumper sponge	1	S <i>MB</i> 265.30 <i>X</i>
Front bumper reinforcement	1	S <i>MB</i> 540.60 <i>X</i>
LH Front bumper fog lamp chrome rim	1	S <i>MB</i> 85.20 <i>✓</i>
LH head lamp inner panel	1	<i>CM</i> S <i>✓</i> 682.80 <i>Presage X</i>
		S 2,861.80
	Less 30%	S 858.54
		S 2,003.26

RH head lamp <i>1343.30</i>	1	Nett	S <i>MB CM</i> 1,477.60 <i>✓</i>
LH head lamp <i>1343.30</i> <i>} 108</i>	1	Nett	S <i>CM</i> 1,477.60 <i>✓</i>
Front grille emblem	1	Nett	S <i>MB</i> 95.80 <i>✓</i>
LH Front bumper fog lamp	1	Nett	S <i>MB</i> 379.00 <i>X</i>
			S 3,430.00
	Less 10%		S 343.00
			S 3,087.00

To remove front damaged parts, to jack out front support panel, front body, and to straighten out front chassis, to reshape and repair LH front fender and inner panel, head lamp inner panel, front support panel, and adjust body panel alignment S 550.00 *400dp*

To spray paint affected front and inner damaged portion inclusive of preparatory works and material S 580.00 *400dp*

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp S 25.00 *201*

S 6,245.26

T/Party: Sompoo Insurance Singapore Pte. Ltd.