

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

16-Jul-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6381 A

1 pc	Rear bumper	\$	696.00 <i>del</i>
1 pc	Rear bumper lower cover	\$	206.00 <i>Kp</i>
1 pc	Rear bumper inner sponge	\$	114.00 <i>?</i>
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00 <i>x</i>
1 pc	Rear bumper reinforcement	\$	607.00 <i>x</i>
2 pcs	Rear bumper stay o/s & n/s @ \$53.00	\$	108.00 <i>x</i>
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00 <i>x</i>
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00 <i>x</i>
2 pcs	Rear bumper n/s & o/s reflector @ \$46.00	\$	92.00 <i>x</i>
		\$	1,953.00
		Less 10%	\$ 195.30
		\$	1,757.70

S/NETT

1 set	Rear bumper clips	\$	48.00 <i>30</i>
1 set	Reverse sensor	\$	200.00 <i>100</i>
	Sundry	\$	50.00 <i>x</i>
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00 <i>30</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 <i>x</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc	\$	650.00 <i>200</i>
	To putty and spray painting on rear bumper, end panel	\$	400.00 <i>200</i>
	To apply rustproofing on the repaired and replaced panels.	\$	80.00 <i>^</i>
		\$	3,485.70

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tanpin 97495749
wp' 21/7/21 @ 11am
4/5 resurvey after repair
tanpin@hhants.com
2 days

maxis
205/65/16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: