

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub. Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570C

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower
Singapore 079909

Attention : Motor Claim Department
Contact : 6389 6111 (main) Fax No. : 6222 1033

Xiao Chen

Estimate : TP21-061

Date : 21/07/2021
Vehicle Num. : SMY7717J
Make/Model : M/Benz GLA180-2016
Chassis/Eng# : WDC1569422J279055/27091031027191
Accident Date : 21/07/2021
Claim No. : SNM21D204001
Reference :
Policy No. : SD21V02098/VPE/R00 (03/01/2022)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	Frt Door Assy RH Distorted		2,398.00 ✓
2.	1	Frt Door Weatherstrip RH New		382.00 ✓
3.	1	Frt Door Channel Rubber RH New		158.00 +
4.	1	Frt Door Mechanism Lock RH New		580.00 +
5.	1	Side Rocker Skirt RH Delc		459.00 ✓
6.	1	Rear Door Pillar RH Repair		1,095.00 +
7.	1	Rear Door RH Distorted		2,514.00 ✓
8.	2	Rear Door Hinge, Top/Lower RH New	168.00	336.00 +
9.	1	Rear Door Center Check RH New		110.00 +
10.	1	Rear Door Weatherstrip RH New		398.00 ✓
11.	1	Rear Door Channel Rubber RH cut		210.00 ✓
12.	1	Rear Door Mechanism Lock RH New		458.00 ✓
13.	1	Rear Door Glass Regulator Gear Assy RH New		768.00 +
14.	1	Rear Door Inner Trim Board RH New		1,217.00 +
15.	12	Rear Door Rivet New	15.00	180.00 50
16.	1	Rear Fender Protector RH cut		321.00 ✓
17.	1	Rear Fender RH Repair		2,610.00 +
18.	1	Rear Fender Inner Liner RH New		230.00 +
19.	1	Rear Bumper Assy Repair		1,560.00 +
20.	2	Rear Bumper Side Holder L/R New	36.00	72.00 +
21.	1	Rear Bumper PDC Parking Sensor New		250.00 +
22.	1	Rear Wheel Bearing w/hub RH New		485.00 +
23.	1	Rear Lower Arm RH New		374.00 +
24.	1	Rear Knuckle Arm RH New		1,398.00 +
25.	1	Rear Shock Absorber RH New		600.00 +
26.	1	Rear Sport Rim cut		900.00 ✓
27.	10 pcs	Rear Bumper Clips New	30.00	300.00 +
28.	8 pcs	Rear Fender RH Inner Liner Clips New	12.00	96.00 +
29.	1	Rear Tyre RH New		450.00 +
List Total S\$:				20,909.00
10.00% Discount S\$:				2,090.90
				18,818.10

8090
7281

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
 Kaki Bukit Autohub. Singapore 417921
 Tel No. : 67461515 / 67471787 Fax No. : 67485015
 Website : www.successunited.com.sg
 Buss. Reg. No. : GST No. 200402570G

China Taiping Insurance (Singapore) Pte. Ltd.
 3 Anson Road #16-00 Springleaf Tower
 Singapore 079909

Attention : Motor Claim Department
 Contact : 6389 6111 (main) Fax No. : 6222 1033

Estimate : TP21-061

Date : 21/07/2021
 Vehicle Num. : SMY7717J
 Make/Model : M/Benz GLA180-2016
 Chassis/Eng# : WDC1569422J279055/27091031027191
 Accident Date : 21/07/2021
 Claim No. : SNM21D204001
 Reference :
 Policy No. : SD21V02098/VPE/R00 (03/01/2022)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

To remove, rearrange electrical wirings, check lighting

~~80.00~~ 30

To remove, replace & transfer door components.

~~500.00~~ 160

To remove, replace rear undercarriage parts.

480.00 *

To remove, repair and replaced damaged bodyparts,
 realign bodyworks & where consistent to the accident

~~2,000.00~~ 800

To putty and respray painting on affected area.

1870

~~1,800.00~~ 800

Wheel Alignment

~~150.00~~ 80

Labour Total S\$:

5,010.00

Total S\$: 23,828.10

=====

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lij
 22/07/21.
 06 Days.

total: 9151

W/S TSK