

ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	18:11HRS
ACCIDENT DATE	19-Jul-21
BUS CAPTAIN NAME	PANG CHEE WAH
THIRD PARTY CLAIM AGAINST	AIG Asia Pacific Insurance Pte. Ltd.

BUS REGISTRATION NUMBER	SMB3502J
BUS TYPE (SD/DD)	DD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	FRONT WINDSCREEN LOWER <i>CRN /</i>	1	\$2,214.98
2	OSF BUMPER <i>CRN /</i>	1	\$395.58
3	OSF LAMP COVER <i>CRN /</i>	1	\$637.90
4	TOWER TRANSIT LOGO "S" <i>NE /</i>	1	\$120.00
5	IU BRACKET <i>NE /</i>	1	\$16.00
6	SIKAFLEX BLACK <i>NE /</i>	<i>tube</i> 5 METRE	\$80.00
7			
8			
		7% GST	\$242.51
		PARTS TOTAL COST	\$3,706.97

SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO DISMANTLE & REPLACE :- <ul style="list-style-type: none"> FRONT WINDSCREEN GLASS OSF BUMPER OSF LAMP COVER 	\$1,300.00 <i>975</i>
TO PERFORM REPAIR WORKS ON :- <ul style="list-style-type: none"> FIBER BODY GLASS PANEL 	\$1,950.00 <i>3230</i> <i>975</i>
SPRAY PAINTING :- <ul style="list-style-type: none"> WHITE & GREY LINING OSF BUMPER FIBER BODY GLASS PANEL 	\$1,920.00 <i>1280</i>
SPRAY PAINTING \$640 PER PANEL	
LABOUR CHARGES \$650 PER DAY	
	7% GST
	LABOUR TOTAL COST

ESTIMATED ACCIDENT REPAIR COST



SECTION 3 : RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST	-
-------------------	---

SECTION 4 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

	DATE IN	19-Jul-2021
	DATE & TIME SURVEY	
	DATE OUT	
BUS TYPE (SD / DD)	DD	
LOSS OF USE COST	TOTAL NUMBER OF DAYS	\$2,000.00

SUMMARY	
SECTION NO.	COST
1	\$3,706.97
2	\$5,531.90
3	-
4	\$2,000.00
TOTAL	\$11,238.87

3464.46
3230.00

6694.46

PAGE 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer .
Signature:
Date:

Rasul
Hp 90010068
4 days
22/07/21 P1025
Resy after repair