

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0596/2021/GW
DATE : 24-Jul-21
WIP : 36383

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 27/7/2021
YOUR INSURED VEH NO : SKS 7490 S

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS PAMELA CHUA SOO PING(CAI SHUPING)
ADDRESS : 371 HOLLAND RD, SERENADE@HOLLAND
#15-03
SINGAPORE 278698
TELEPHONE : HP +65 9651 7373
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT/00795858/01
VEHICLE NO : **SLN 7013 B**
MODEL CODE : A4 1.4 TFSI S TRONIC
MODEL YEAR : 15/5/2017
ENGINE NO : CVN034907
CHASSIS NO : WAUZZZF40HA135400
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Jul-21
PLACE OF ACCIDENT : CAR PARK OF GREAT WORLD CITY

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 7013 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 2,100.00	500
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,002.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 7013 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Deformed</i>	1	\$ 2,111.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	TBC	x
3	FRONT BUMPER SECURING STRIP <i>new</i>	2	\$ 71.00	x
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 210.00	x
5	RADIATOR AIR GUIDE RH <i>new</i>	1	\$ 63.00	x
6	FRONT AIR GUIDE GRILLE RH <i>new</i>	1	\$ 135.00	x
7	FRONT BUMPER GUIDE SECTION RH <i>?</i>	1	\$ 38.00	?
8	FRONT FENDER RH <i>Repair</i>	1	\$ 767.00	x
9	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 202.00	+
10	FRONT FENDER CLOSING ELEMENT RH <i>new</i>	1	\$ 72.00	+
11	FRONT FENDER BRACKET RH <i>new</i>	1	\$ 35.00	+
12	FRONT FENDER BRACE RH <i>new</i>	1	\$ 118.00	+
13	FRONT FENDER DEFORMATION ELEMENT RH <i>new</i>	1	\$ 49.00	x
14	FRONT FENDER POP RIVET <i>not rec</i>	6	\$ 20.00	+
15	FRONT WHEEL HOUSING LINER RH <i>not rec</i>	1	\$ 241.00	+
16	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS RH <i>not rec</i>	1	TBC	x
17	FRONT WHEEL SPOILER RH <i>not rec</i>	1	\$ 73.00	x
18	FRONT FENDER LEDGE COVER RH <i>not rec</i>	1	\$ 23.00	x
19	LED HEADLIGHT RH <i>not rec</i>	1	\$ 7,693.00	x
20	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM <i>not rec</i>	1	\$ 210.00	x
21	SUNDRIES <i>?</i>		\$ 250.00	?
TOTAL SPARE PARTS			\$ 12,381.00	
TOTAL LABOUR CHARGES			\$ 5,002.00	
GRAND TOTAL			\$ 17,383.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King -*
SURVEYED DATE : *27/07/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT