



7828/Ag



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0596/2021/GW
DATE : 24-Jul-21
WIP : 36383

Cecilia
\$3480.80

CONFIRM WITH ADRIAN ON
31/12/2021

4 Days

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 27/7/2021

YOUR INSURED VEH NO : SKS 7490 S

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS PAMELA CHUA SOO PING(CAI SHUPING)
ADDRESS : 371 HOLLAND RD, SERENADE@HOLLAND
#15-03
SINGAPORE 278698
TELEPHONE : HP +65 9651 7373
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT/00795858/01
VEHICLE NO : SLN 7013 B
MODEL CODE : A4 1.4 TFSI S TRONIC
MODEL YEAR : 15/5/2017
ENGINE NO : CVN034907
CHASSIS NO : WAUZZZF40HA135400
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Jul-21
PLACE OF ACCIDENT : CAR PARK OF GREAT WORLD CITY

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 7013 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	X
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 2,100.00	500
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,002.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 7013 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Deformed</i>	1	\$ 2,111.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	TBC	X
3	FRONT BUMPER SECURING STRIP <i>new</i>	2	\$ 71.00	X
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 210.00	X
5	RADIATOR AIR GUIDE RH <i>new</i>	1	\$ 63.00	X
6	FRONT AIR GUIDE GRILLE RH <i>new</i>	1	\$ 135.00	X
7	FRONT BUMPER GUIDE SECTION RH <i>new</i>	1	\$ 38.00	X
8	FRONT FENDER RH <i>Repair</i>	1	\$ 767.00	X
9	FRONT FENDER ATTACHMENT PARTS <i>new</i>	1	\$ 202.00	+
10	FRONT FENDER CLOSING ELEMENT RH <i>new</i>	1	\$ 72.00	+
11	FRONT FENDER BRACKET RH <i>new</i>	1	\$ 35.00	+
12	FRONT FENDER BRACE RH <i>new</i>	1	\$ 118.00	+
13	FRONT FENDER DEFORMATION ELEMENT RH <i>new</i>	1	\$ 49.00	X
14	FRONT FENDER POP RIVET <i>new</i>	6	\$ 20.00	+
15	FRONT WHEEL HOUSING LINER RH <i>new</i>	1	\$ 241.00	+
16	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS RH <i>new</i>	1	TBC	X
17	FRONT WHEEL SPOILER RH <i>new</i>	1	\$ 73.00	X
18	FRONT FENDER LEDGE COVER RH <i>new</i>	1	\$ 23.00	X
19	LED HEADLIGHT RH <i>new</i>	1	\$ 7,693.00	X
20	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM <i>new</i>	1	\$ 210.00	X
21	SUNDRIES <i>new</i>		\$ 250.00	X
TOTAL SPARE PARTS			\$ 12,381.00	
TOTAL LABOUR CHARGES			\$ 5,002.00	
GRAND TOTAL			\$ 17,383.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King -
SURVEYED DATE : 27/07/21.
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 03 days. fls.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT