



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS/CTI21007833/c	
			Date: 22/07/2021	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 9362B	Veh. Inspected	SJW 4853P	
Policy No.		Coverage (\$)	0.00	
Claim No.	SNM21D203916/C02/YN9362B/ THAMYL	Excess (\$)	0.00	
Assign From	PAULINE THAM	Assign Date	22/07/2021	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/07/2021	Inspection Date	22/07/2021	
Survey held at	Blk 5035 Ang Mo Kio Industrial Park 2,, #01-367			
Repairer	GOLDBELL ENGINEERING PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

27.07.2021 4.05pm Hi LKK, Please note that third party had withdrawn their claim.
Please let us know if any work done for our closure. - Pauline Tham

27.07.2021 4.21pm Dear Pauline, Noted with thanks. No survey was done for the vehicle.
We will close this file at our end without billing. - Yan *Celine 27.07.2021*