

ASS. REC. BY:

REF:

TII /

ASSIGNMENT

Kenneth

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SIDO 9434

Yr Regn:

08, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Wish

c.c.

1794

Colour

Red

A/C: Insured / Std / NI / NA

Sp. Reading

703766

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDER12W203002821

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fairken

Front

Rear

R/Bal.

8

mm

R/Bal.

5

mm

L/Bal.

8

mm

L/Bal.

5

mm

D.O.A.

137815

D.O.I.

14/8/15

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S/M

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

17/8 Est not ready
File pass to Catherine

215 \$ 1650 (Red \$ 5176.17 / 76%).

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Report Format:

Lump Sum / I.B.I.: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Other

TOTAL

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD 943M - III

RIZA

Not Attached
11 Sep @ 165ch

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 943M - RIZA
JTDER12W203002821
TOYOTA
WISH 1.8 BI-FUEL
13.08.2015
III

PART		LIST	
1	1	Front Bumper	\$ 487.80 ✓
2	1	Front Bumper Lower Absorber	\$ 105.00 ✓
3	1	Front Bumper Reinforcement	\$ 270.00 ✓
4	1	Front Bumper Side Retainer RH	\$ 57.30 ✓
5	1	Front Headlamp RH	\$ 672.00 ✓
6	1	Front Fender RH	\$ 698.00 ✓
7	1	Front Fender Liner RH	\$ 307.62 X
8	1	Radiator Grille	\$ 169.80 X
9	1	Windscreen washer tank	\$ 138.33 X
10	1	Windscreen washer tank motor	\$ 222.38 X
TOTAL		\$	3,128.23
25%		\$	782.06
		\$	2,346.17

Special Nett

1 Set	Bumper Fastener Clip FRT	\$	35.00 ✓
1 Set	Front Fender Liner Fastener Clip	\$	20.00 X
1	CNG Sticker	\$	30.00 15 Jan
1	Front Fender Advertisement Sticker RH	\$	250.00 15 Jan
1	Front tyre RH	\$	180.00 X
1	Front tyre rim RH	\$	120.00 X
1	Hub cap RH	\$	35.00 X
TOTAL		\$	670.00
TOTAL PARTS		\$	3,016.17

Panel Beating, Knocking And Straightening The
 Necessary Portion, Remove And Renewal Of
 Parts, Adjust And Realign The Same

\$ 1,400.00 300

To Rust-Proofing Of The Affected Areas.

\$ 220.00 300

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD 943M - III

RIZA

Putty And Spray Painting Of the Affected Portion.	\$	1,350.00	4ed
To Check Electrical Lighting Concerned.	\$	120.00	2ol
To remove and replace corporate sticker	\$	330.00	3ol
To check steering geometry and computer wheel alignment	\$	220.00	6ol
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	1

TOTAL \$ 3,810.00

Over All Total \$ 6,826.17

Repair days

5 DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting.
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation.
- Third party survey is on a "Without Prejudice" basis.
- No illegal modification(s) is allowed.
- Supplementary item(s) must be resurveyed. This is subject to final approval from Insurance Co.

Acknowledged by Repairer

Signature:

Date:

Hsiao Tong

From: Hsiao Tong
Sent: Monday, 31 August, 2015 5:22 PM
To: 'JasmineTan' (jasminetan@transcabservices.com.sg); Zhe Wei (zhewei.kek@transcabservices.com.sg); claims@transcabservices.com.sg
Subject: <Request for Video Footage> DOA: 13/08/2015; Your ref: SHD 943M *Our Ref: CC3/III15013900/Kpa3 [ACCIDENT INVOLVING SHC 6194Z & SHD 943M]
Attachments: The statement of SHC 6194Z.pdf

Your ref: **SHD 943M**
Our Ref: CC3/III15013900/Kpa3

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING SHC 6194Z & SHD 943M ON 13/08/2015

We refer to the above matter.

Please be informed that liability is unclear for this matter. Our insured reported that your client was exiting from Chinatown point and hit onto his taxi while he was filtering to the extreme left lane. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request a copy of video footage as stated in your client's accident report in order for us to look into the matter.

We shall revert upon hearing from you.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Hsiao Tong Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong

From: Zhe Wei <zhewei.kek@transcabservices.com.sg>
Sent: Thursday, 3 September, 2015 3:20 PM
To: Hsiao Tong
Cc: "JasmineTan"; claims@transcabservices.com.sg
Subject: RE: <Request for Video Footage> DOA: 13/08/2015; Your ref: SHD 943M *Our Ref: CC3/III15013900/Kpa3 [ACCIDENT INVOLVING SHC 6194Z & SHD 943M]

Hi Hsiao Tong,

Please follow the link below to the requested footage:-

<https://www.dropbox.com/s/67vhlp7vah2qef4/SHD943M%20130815.AVI?dl=0>

Thank you.

Kindly quote our reference in your future replies to us.

Best Regards,
Kek Zhewei

From: Hsiao Tong [mailto:chewht@lkkauto.com]
Sent: Monday, August 31, 2015 5:22 PM
To: 'JasmineTan' (jasminetan@transcabservices.com.sg) <jasminetan@transcabservices.com.sg>; Zhe Wei (zhewei.kek@transcabservices.com.sg) <zhewei.kek@transcabservices.com.sg>; claims@transcabservices.com.sg
Subject: <Request for Video Footage> DOA: 13/08/2015; Your ref: SHD 943M *Our Ref: CC3/III15013900/Kpa3 [ACCIDENT INVOLVING SHC 6194Z & SHD 943M]

Your ref: **SHD 943M**
Our Ref: CC3/III15013900/Kpa3

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING SHC 6194Z & SHD 943M ON 13/08/2015

We refer to the above matter.

Please be informed that liability is unclear for this matter. Our insured reported that your client was exiting from Chinatown point and hit onto his taxi while he was filtering to the extreme left lane. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request a copy of video footage as stated in your client's accident report in order for us to look into the matter.

We shall revert upon hearing from you.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: MCP141598/SN
Our Ref: CC3/III15013900/Kpa3

21 September 2015

India International Insurance Pte Ltd
64 Cecil Street
#04/#05 IOB Building
Singapore 049711

Attn : Ms Sundari Nagarajan

Dear Sir/Madam,

ACCIDENT INVOLVING SHC 6194Z(OI) & SHD 943M(TP) ON 13/08/2015

We refer to the above matter.

Enclosed here with the video footage from third party for your perusal.

Please call us if you have further queries.

Yours faithfully

Chew Hsiao Tong
Claims Section
DID: 6742 3197
Fax: 6741 4108
E-mail: chewht@lkkauto.com

Print Sent Message

This mail is associated with :

***SHD943M (MCP141598/SN)
[SHC6194Z]**

TP
TRANS-CAB SERVICES PTE LTD
Aug 13 2015 12:00PM

Trans-cab Auto Services Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 18/09/2015 08:51 AM.
To sundari@iii.com.sg
CC motorclaim@iii.com.sg; chewht@lkkauto.com
Subject PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

PODS – Express Settlements

PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

We refer to the above matter.

TP reported that he was travelling along New Bridge Road towards Kampong Bahru on the most left lane. When he was travelling near to Chinatown point, suddenly OI changed into his lane from the right and hit onto TP's taxi.

OI reported that he slowed down with his left indicator on before he filtering into the bus lane. OI noticed that TP who was exiting from Chinatown Point, stopped and gave way to him(giving hand signal to proceed). While OI was filtering into the extreme left lane, suddenly he felt an impact from his left and discovered that TP moved off ahead and hit him.

TP submitted a copy of the video footage for our consideration.(A copy of the video will be sent to your good office by next week). The video footage shown that TP was exiting from minor road and collided with OI who was changing lane from the right to left on main road as resulted the collision. We are of the opinion that TP should exercise greater caution while turning out from minor road.

In view of this, we are intending to reject third party claim.

For your approval/instruction/comments.

Best Regards,

Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SHD943M (MCP141598/SN)
[SHC6194Z]**

TP
TRANS-CAB SERVICES PTE LTD
Aug 13 2015 12:00PM

Trans-cab Auto Services Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on **18/09/2015 14:50 PM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SHD943M - Claim Handler: Sundari Nagarajan

Approved:0.00.

DOCUMENTS SUMMARY

There are no documents.

Hsiao Tong

From: Hsiao Tong
Sent: Wednesday, 7 October, 2015 10:46 AM
To: 'JasmineTan' (jasminetan@transcabservices.com.sg); Zhe Wei (zhewei.kek@transcabservices.com.sg); claims@transcabservices.com.sg
Subject: DOA: 13/08/2015; Your ref: SHD 943M *Our Ref: CC3/III15013900/Kpa3 [ACCIDENT INVOLVING SHC 6194Z & SHD 943M]

Your ref: **SHD 943M**
Our Ref: CC3/III15013900/Kpa3

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING SHC 6194Z & SHD 943M ON 13/08/2015

We refer to the above matter.

Our insured driver has reiterated that the accident was caused due to the entire negligence of your client. Your client turned out from minor road and hit onto our insured who was driving on main road. We are of the opinion that your client should exercise greater caution while turning out from minor road.

Under such a circumstances, we have our principal instruction to deny liability and unable to look into your client's claim.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong

From: tzeyong.lui <tzeyong.lui@transcabservices.com.sg>
Sent: Wednesday, 7 October, 2015 2:24 PM
To: Hsiao Tong
Cc: jasminetan@transcabservices.com.sg; zhewei.kek@transcabservices.com.sg; claims@transcabservices.com.sg
Subject: RE: 13/08/2015; Our ref: AAD1508-153 & Veh No :-SHD 943M *Your Ref: CC3/III15013900/Kpa3 [ACCIDENT INVOLVING SHC 6194Z & SHD 943M]
Attachments: SHD943M-DOA-13.08.15.AVI.wmv

Dear Hsiao Tong,

Kindly convey to your principal –India Ins. to withdraw this deny liability for this case.

We have attached the video clip for you to investigate this matter and to review this case again.

You can see our taxi driver turned out from China Town Point complex pick-up exit out and did not hit onto the Silver Cab SHC6194Z.

While our Trans Cab Taxi SHD943M already at the extreme left lane (ie the dotted bus lane) traveling straight at that position and behind the SBS Transit Bus; the silver cab (SHC6194Z) just cut suddenly into the extreme left lane without due consideration and collided on the front right portion of our transcab taxi SHD943M in which our taxi is already traveling straight and behind the SBS Transit bus.

My opinion is that the silver Cab is held full responsible for this accident without due consideration of others road user.

Kindly request your principle insurer (ie. India Insurer) to review this case again and to with draw the deny liability and to compensate full damages to us & our taxi driver.

We appreciate.

Thank you & Best Regards,

Lui Tze Yong
TRANS-CAB AUTO SERVICES PTE LTD
(Accounts)
tzeyong.lui@transcabservices.com.sg
Tel: 66031265 Ext.232

*Maintain record ?
other sig. ?*

From: Hsiao Tong [mailto:chewht@lkkauto.com]
Sent: Wednesday, October 07, 2015 10:46 AM
To: 'JasmineTan' (jasminetan@transcabservices.com.sg); Zhe Wei (zhewei.kek@transcabservices.com.sg); claims@transcabservices.com.sg
Subject: DOA: 13/08/2015; Your ref: SHD 943M *Our Ref: CC3/III15013900/Kpa3 [ACCIDENT INVOLVING SHC 6194Z & SHD 943M]

Your ref: **SHD 943M**
Our Ref: CC3/III15013900/Kpa3

WITHOUT PREJUDICE

Dear Sir/Madam,

ACCIDENT INVOLVING SHC 6194Z & SHD 943M ON 13/08/2015

We refer to the above matter.

Our insured driver has reiterated that the accident was caused due to the entire negligence of your client. Your client turned out from minor road and hit onto our insured who was driving on main road. We are of the opinion that your client should exercise greater caution while turning out from minor road.

View Sent Message

This mail is associated with :

*SHD943M (MCP141598/SN)
[SHC6194Z]

TP

TRANS-CAB SERVICES PTE LTD
Aug 13 2015 12:00PM

Trans-cab Auto Services Pte Ltd

Resend View Recipients Print Message Delete Message Forward

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 17/11/2015 10:49 AM.
To sundari@iii.com.sg
CC motorclaim@iii.com.sg; chewht@lkkauto.com
Subject PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to the above matter.

We have rejected TP claim as per instruction. However TP appeal for this matter.

According to TP, their taxi driver turned out from China Town Point complex pick-up exit out and did not hit onto OI. While TP already at the extreme left lane (ie the dotted bus lane) traveling straight at that position and behind the SBS Transit Bus; OI just cut suddenly into the extreme left lane without due consideration and collided on the front right portion of TP taxi in which TP is already traveling straight and behind the SBS Transit bus.

Kindly let us have your instruction if we shall maintain rejection or propose settlement at 50% or else advise further instruction.

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

<- Original Message ->

From: LKK_HQ
To: sundari@iii.com.sg
CC: motorclaim@iii.com.sg; chewht@lkkauto.com
Sent On: 18/09/2015 08:51 AM
Subject: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

PODS – Express Settlements

PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

We refer to the above matter.

TP reported that he was travelling along New Bridge Road towards Kampong Bahru on the most left lane. When he was travelling near to Chinatown point, suddenly OI changed into his lane from the right and hit onto TP's taxi.

OI reported that he slowed down with his left indicator on before he filtering into the bus lane. OI noticed that TP who was exiting from Chinatown Point, stopped and gave way to him(giving hand signal to proceed). While OI was filtering into the extreme left lane, suddenly he felt an impact from his left and discovered that TP moved off ahead and hit him.

TP submitted a copy of the video footage for our consideration.(A copy of the video will be sent to your good office by next week). The video footage shown that TP was exiting from minor road and collided with OI who was changing lane from the right to left on main road as resulted the collision. We are of the opinion that TP should exercise greater caution while turning out from minor road.

In view of this, we are intending to reject third party claim.

For your approval/instruction/comments.

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.

Print Sent Message

This mail is associated with :

*SHD943M (MCP141598)
[SHC6194Z]

TP

TRANS-CAB SERVICES PTE LTD

Aug 13 2015 12:00PM

[PREMIER TAXIS PTE LTD]

Trans-cab Auto Services Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 18/04/2016 08:44 AM.
To sundari@iii.com.sg
CC chewht@lkkauto.com; III_SG
Subject RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

TP appeal the matter.

Kindly let us have your further instruction as TP is chasing for it. Otherwise, they may pass the case to lawyer for further handling.

Hsiao Tong
LKK Auto Consultants Pte Ltd
DID: 6742 3197

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: III_SG; chewht@lkkauto.com
Sent On: 23/01/2016 04:40 PM
Subject: RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

Kindly advise.

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: III_SG; chewht@lkkauto.com
Sent On: 31/12/2015 08:13 AM
Subject: RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

Kindly advise.

Best Regards,

Print Sent Message

This mail is associated with :

***SHD943M (MCP141598)
[SHC6194Z]**

TP

TRANS-CAB SERVICES PTE LTD

Aug 13 2015 12:00PM

[PREMIER TAXIS PTE LTD]

Trans-cab Auto Services Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 20/09/2016 08:20 AM.
To sundari@iii.com.sg
CC III_SG; motorclaim@iii.com.sg; chewht@lkkauto.com
Subject RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

TP appeal the matter.

Kindly let us have your further instruction as TP is chasing for it. Otherwise, they may pass the case to lawyer for further handling.

Hsiao Tong
LKK Auto Consultants Pte Ltd
DID: 6742 3197

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: chewht@lkkauto.com; III_SG
Sent On: 18/04/2016 08:44 AM
Subject: RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

TP appeal the matter.

Kindly let us have your further instruction as TP is chasing for it. Otherwise, they may pass the case to lawyer for further handling.

Hsiao Tong
LKK Auto Consultants Pte Ltd
DID: 6742 3197

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: III_SG; chewht@lkkauto.com
Sent On: 23/01/2016 04:40 PM
Subject: RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

Kindly advise.

Best Regards,
Hsiao Tong, Chew | Case Handler

Print Sent Message

This mail is associated with :

***SHD943M (MCP141598)
[SHC6194Z]**

TP

TRANS-CAB SERVICES PTE LTD

Aug 13 2015 12:00PM

[PREMIER TAXIS PTE TLD]

Trans-cab Auto Services Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 12/11/2016 08:08 AM.
To sundari@iii.com.sg
CC chewht@lkkauto.com; III_SG; motorclaim@iii.com.sg
Subject RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

We have rejected TP claim as per instruction. However TP appeal for this matter.

According to TP, their taxi driver turned out from China Town Point complex pick-up exit out and did not hit onto OI. While TP already at the extreme left lane (ie the dotted bus lane) traveling straight at that position and behind the SBS Transit Bus; OI just cut suddenly into the extreme left lane without due consideration and collided on the front right portion of TP taxi in which TP is already traveling straight and behind the SBS Transit bus.

Kindly let us have your instruction if we shall maintain rejection or propose settlement at 50% or else advise further instruction as TP is chasing for offer. Otherwise, they may pass the case to lawyer for further handling.

Hsiao Tong
LKK Auto Consultants Pte Ltd
DID: 6742 3197

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: III_SG; motorclaim@iii.com.sg; chewht@lkkauto.com
Sent On: 20/09/2016 08:20 AM
Subject: RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

TP appeal the matter.

Kindly let us have your further instruction as TP is chasing for it. Otherwise, they may pass the case to lawyer for further handling.

Hsiao Tong
LKK Auto Consultants Pte Ltd
DID: 6742 3197

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: chewht@lkkauto.com; III_SG
Sent On: 18/04/2016 08:44 AM
Subject: RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

TP appeal the matter.

Kindly let us have your further instruction as TP is chasing for it. Otherwise, they may pass the case to lawyer for further handling.

Hsiao Tong
LKK Auto Consultants Pte Ltd
DID: 6742 3197

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: III_SG; chewht@lkkauto.com
Sent On: 23/01/2016 04:40 PM
Subject: RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

Kindly advise.

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: III_SG; chewht@lkkauto.com
Sent On: 31/12/2015 08:13 AM
Subject: RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

Kindly advise.

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: III_SG; chewht@lkkauto.com
Sent On: 15/12/2015 10:44 AM
Subject: Fw: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

Kindly advise.

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg

CC: motorclaim@iii.com.sg; chewht@lkkauto.com

Sent On: 17/11/2015 10:49 AM

Subject: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to the above matter.

We have rejected TP claim as per instruction. However TP appeal for this matter.

According to TP, their taxi driver turned out from China Town Point complex pick-up exit out and did not hit onto OI. While TP already at the extreme left lane (ie the dotted bus lane) traveling straight at that position and behind the SBS Transit Bus; OI just cut suddenly into the extreme left lane without due consideration and collided on the front right portion of TP taxi in which TP is already traveling straight and behind the SBS Transit bus.

Kindly let us have your instruction if we shall maintain rejection or propose settlement at 50% or else advise further instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

<-- Original Message -->

From: LKK_HQ

To: sundari@iii.com.sg

CC: motorclaim@iii.com.sg; chewht@lkkauto.com

Sent On: 18/09/2015 08:51 AM

Subject: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

PODS – Express Settlements

PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

We refer to the above matter.

TP reported that he was travelling along New Bridge Road towards Kampong Bahru on the most left lane. When he was travelling near to Chinatown point, suddenly OI changed into his lane from the right and hit onto TP's taxi.

OI reported that he slowed down with his left indicator on before he filtering into the bus lane. OI noticed that TP who was exiting from Chinatown Point, stopped and gave way to him(giving hand signal to proceed). While OI was filtering into the extreme left lane, suddenly he felt an impact from his left and discovered that TP moved off ahead and hit him.

TP submitted a copy of the video footage for our consideration.(A copy of the video will be sent to your good office by next week). The video footage shown that TP was exiting from minor road and collided with OI who was changing lane from the right to left on main road as resulted the collision. We are of the opinion that TP should exercise greater caution while turning out from minor road.

In view of this, we are intending to reject third party claim.

For your approval/instruction/comments.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Sent Message

This mail is associated with :

***SHD943M (MCP141598)**

[SHC6194Z]

TP

TRANS-CAB SERVICES PTE LTD

Aug 13 2015 12:00PM

[PREMIER TAXIS PTE TLD]

Trans-cab Auto Services Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 29/12/2016 10:33 AM.
To sundari@iii.com.sg
CC chewht@lkkauto.com; III_SG
Subject RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

Further to our below email.

Kindly let us have your instruction if we shall maintain rejection or propose settlement at 50% or else advise further instruction as TP is chasing for offer. Otherwise, they may pass the case to lawyer for further handling.

Hsiao Tong
LKK Auto Consultants Pte Ltd
DID: 6742 3197

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: chewht@lkkauto.com; III_SG; motorclaim@iii.com.sg
Sent On: 12/11/2016 08:08 AM
Subject: RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

We have rejected TP claim as per instruction. However TP appeal for this matter.

According to TP, their taxi driver turned out from China Town Point complex pick-up exit out and did not hit onto OI. While TP already at the extreme left lane (ie the dotted bus lane) traveling straight at that position and behind the SBS Transit Bus; OI just cut suddenly into the extreme left lane without due consideration and collided on the front right portion of TP taxi in which TP is already traveling straight and behind the SBS Transit bus.

Kindly let us have your instruction if we shall maintain rejection or propose settlement at 50% or else advise further instruction as TP is chasing for offer. Otherwise, they may pass the case to lawyer for further handling.

Hsiao Tong
LKK Auto Consultants Pte Ltd
DID: 6742 3197

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: III_SG; motorclaim@iii.com.sg; chewht@lkkauto.com
Sent On: 20/09/2016 08:20 AM
Subject: RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

Print Sent Message

This mail is associated with :

***SHD943M (MCP141598)
[SHC6194Z]**

TP

TRANS-CAB SERVICES PTE LTD

Aug 13 2015 12:00PM

[PREMIER TAXIS PTE TLD]

Trans-cab Auto Services Pte Ltd

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 25/02/2017 13:23 PM.
To sundari@iii.com.sg
CC chewht@lkkauto.com; III_SG
Subject RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

Further to our below email,

We will proceed to close our file and submit survey report to you good office.

Thank you.

Hsiao Tong
LKK Auto Consultants Pte Ltd

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: chewht@lkkauto.com; III_SG
Sent On: 29/12/2016 10:33 AM
Subject: RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

Further to our below email.

Kindly let us have your instruction if we shall maintain rejection or propose settlement at 50% or else advise further instruction as TP is chasing for offer. Otherwise, they may pass the case to lawyer for further handling.

Hsiao Tong
LKK Auto Consultants Pte Ltd
DID: 6742 3197

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: chewht@lkkauto.com; III_SG; motorclaim@iii.com.sg
Sent On: 12/11/2016 08:08 AM
Subject: RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

We have rejected TP claim as per instruction. However TP appeal for this matter.

According to TP, their taxi driver turned out from China Town Point complex pick-up exit out and did not hit onto OI. While TP already at the extreme left lane (ie the dotted bus lane) traveling straight at that position and behind the SBS Transit Bus; OI just cut suddenly into the extreme left lane without due consideration and collided on the front right portion of TP taxi in which TP is already traveling straight and behind the SBS Transit bus.

Kindly let us have your instruction if we shall maintain rejection or propose settlement at 50% or else advise further instruction as TP is chasing for offer. Otherwise, they may pass the case to lawyer for further handling.

Hsiao Tong
LKK Auto Consultants Pte Ltd
DID: 6742 3197

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: III_SG; motorclaim@iii.com.sg; chewht@lkkauto.com
Sent On: 20/09/2016 08:20 AM
Subject: RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

TP appeal the matter.

Kindly let us have your further instruction as TP is chasing for it. Otherwise, they may pass the case to lawyer for further handling.

Hsiao Tong
LKK Auto Consultants Pte Ltd
DID: 6742 3197

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: chewht@lkkauto.com; III_SG
Sent On: 18/04/2016 08:44 AM
Subject: RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

TP appeal the matter.

Kindly let us have your further instruction as TP is chasing for it. Otherwise, they may pass the case to lawyer for further handling.

Hsiao Tong
LKK Auto Consultants Pte Ltd
DID: 6742 3197

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: III_SG; chewht@lkkauto.com
Sent On: 23/01/2016 04:40 PM
Subject: RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

Kindly advise.

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: III_SG; chewht@lkkauto.com
Sent On: 31/12/2015 08:13 AM
Subject: RE: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

Kindly advise.

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: III_SG; chewht@lkkauto.com
Sent On: 15/12/2015 10:44 AM
Subject: Fw: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to our email dated 17/11/2015.

Kindly advise.

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: motorclaim@iii.com.sg; chewht@lkkauto.com
Sent On: 17/11/2015 10:49 AM
Subject: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

Dear Sundari,

We refer to the above matter.

We have rejected TP claim as per instruction. However TP appeal for this matter.

According to TP, their taxi driver turned out from China Town Point complex pick-up exit out and did not hit onto OI. While TP already at the extreme left lane (ie the dotted bus lane) traveling straight at that position and behind the SBS Transit Bus; OI just cut suddenly into the extreme left lane without due consideration and collided on the front right portion of TP taxi in which TP is already traveling straight and behind the SBS Transit bus.

Kindly let us have your instruction if we shall maintain rejection or propose settlement at 50% or else advise further instruction.

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

<-- Original Message -->

From: LKK_HQ
To: sundari@iii.com.sg
CC: motorclaim@iii.com.sg; chewht@lkkauto.com
Sent On: 18/09/2015 08:51 AM
Subject: PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

PODS – Express Settlements

PODS III Ref: MCP141598/SN LKK Ref: CC3/III15013900/Kpa3 Accident on 13.08.2015 involving SHC 6194Z(India) and SHD 943M(TP) along/at New Bridge Road

We refer to the above matter.

TP reported that he was travelling along New Bridge Road towards Kampong Bahru on the most left lane. When he was travelling near to Chinatown point, suddenly OI changed into his lane from the right and hit onto TP's taxi.

OI reported that he slowed down with his left indicator on before he filtering into the bus lane. OI noticed that TP who was exiting from Chinatown Point, stopped and gave way to him(giving hand signal to proceed). While OI was filtering into the extreme left lane, suddenly he felt an impact from his left and discovered that TP moved off ahead and hit him.

TP submitted a copy of the video footage for our consideration.(A copy of the video will be sent to your good office by next week). The video footage shown that TP was exiting from minor road and collided with OI who was changing lane from the right to left on main road as resulted the collision. We are of the opinion that TP should exercise greater caution while turning out from minor road.

In view of this, we are intending to reject third party claim.

For your approval/instruction/comments.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Aug 2015 Edit Reg		14 Aug 2015 00:00 Edit Adj Rpt	S\$1,650.00 Edit Estimates	S\$1,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	PREMIER TAXIS PTE TLD, Co. Reg. No.: 200304975H		
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Vehicle Reg. No.:	SHD943M	Date of Loss:	13/08/2015 12:00 - :59
Claim Type:	TP / MCP141598	Policy/Cover Note No.:	MPRE0003 (Third Party Only)
Vehicle Reg. No. (Insured):	SHC6194Z	Policy No. (Claimant):	D-12047359MFSH/3925
		Excess:	
Repairer:	Trans-cab Auto Services Pte Ltd (HQ) No. 42 Sungei Kadut St 1, 729346 Sungei Kadut - Tel: 62876666		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]		
Claimant's Insurer:	First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 26/08/2015]		
Driver/Custodian (Insured):	LOW SWEE KUAN (), NRIC: S7221970H		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- III_SG (18/09/2015): Alert - Adj Mandate Approved (S\$0.00) - SHD943M - Claim Handler: Sundari Nagaraj...

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHD943M (MCP141598)
[SHC6194Z]
TP
TRANS-CAB SERVICES PTE LTD
Aug 13 2015 12:00PM
[PREMIER TAXIS PTE TLD]
Trans-cab Auto Services Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View Use Viewer	
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	07/10/15 10:41	General View		Load JPG	<input checked="" type="checkbox"/>			
2	07/10/15 10:41	General View		Load JPG	<input checked="" type="checkbox"/>			
3	07/10/15 10:41	General View		Load JPG	<input checked="" type="checkbox"/>			
4	07/10/15 10:41	General View		Load JPG	<input checked="" type="checkbox"/>			
5	07/10/15 10:41	General View		Load JPG	<input checked="" type="checkbox"/>			
6	07/10/15 10:41	General View		Load JPG	<input checked="" type="checkbox"/>			
7	07/10/15 10:41	General View		Load JPG	<input checked="" type="checkbox"/>			
8	07/10/15 10:41	General View		Load JPG	<input checked="" type="checkbox"/>			
9	07/10/15 10:41	General View		Load JPG	<input checked="" type="checkbox"/>			
10	07/10/15 10:41	General View		Load JPG	<input checked="" type="checkbox"/>			
11	07/10/15 10:41	General View		Load JPG	<input checked="" type="checkbox"/>			
12	07/10/15 10:41	General View		Load JPG	<input checked="" type="checkbox"/>			
13	07/10/15 10:41	General View		Load JPG	<input checked="" type="checkbox"/>			
14	07/10/15 10:41	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>			
15	07/10/15 10:41	Chassis Number		Load JPG	<input checked="" type="checkbox"/>			
Documentation							1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	08/09/15 14:53	TP GIA REPORT		Load PDF				
2	07/10/15 10:37	TP ESTIMATE		Load PDF				
3	07/10/15 10:47	Email to TP wksp_reject dd 071015		Load PDF				
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print			
1	18/08/15 15:47	IV - Singapore Accident Statement		Load PDF				

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III15013900/KPA3Q2

Date: 14/03/2017

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MPRE0003
 Claimant Vehicle No: SHD943M Insured Vehicle No: SHC6194Z
 Date of Loss: 13/08/2015 Nature of Claim: TP Claim No: MCP141598

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD943M
 Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ3237878
 Reg. Date: 31/08/2009 (Man. Year: 2009) Chassis No: JTDER12W203002821
 Colour: Red Odometer: 703766 km
 Engine Capacity: 1794 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Falken 8 mm Rear Left Side: Falken 5 mm
 Front Right Side: Falken 8 mm Rear Right Side: Falken 5 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,016.17	1,227.50	1,788.67	59.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,810.00	840.00	2,970.00	77.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,826.17	2,067.50	4,758.67	69.71
Approved Total (Overridden) (S\$)		1,650.00		
(S\$)	6,826.17	1,650.00	5,176.17	75.83
+ GST 7.00/7.00% (S\$)	477.83	115.50	362.33	75.83
Nett Amount (S\$)	7,304.00	1,765.50	5,538.50	75.83

INSPECTION

Date of Assignment: 14/08/2015
 Date Inspected: 14/08/2015 Inspected At: Trans-cab Auto Services Pte Ltd (HQ)
 No. 42 Sungei Kadut St 1
 Singapore 729346
 Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 14 Mar 2017)	
Parts:	N/A	TOYOTA WISH 1.8 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD943M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	487.80 FL	*- FL
2	1		*FRONT BUMPER LOWER ABSORBER	Serviceable	105.00 FL	*- FL
3	1		*FRONT BUMPER REINFORCEMENT	Repair	270.00 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER RH	Serviceable	57.30 FL	*- FL
5	1		*FRONT HEADLAMP RH	Mtg Cracked	672.00 FL	*672.00 FL
6	1		*FRONT FENDER RH	Bent	698.00 FL	*698.00 FL
7	1		*FRONT FENDER LINER RH	Serviceable	307.62 FL	*- FL
8	1		*RADIATOR GRILLE	Serviceable	169.80 FL	*- FL
9	1		*WINDSCREEN WASHER TANK	Serviceable	138.33 FL	*- FL
10	1		*WINDSCREEN WASHER TANK MOTOR	Serviceable	222.38 FL	*- FL
11	1		*SET BUMPER FASTENER CLIP FRT	Necessary	35.00 FS	*35.00 FS
12	1		*SET FRONT FENDER LINER FASTENER CLIP	Not Necessary	20.00 FS	*- FS
13	1		*CNG STICKER	Necessary	30.00 FS	*15.00 FS
14	1		*FRONT FENDER ADVERTISEMEN STICKER RH	Necessary	250.00 FS	*150.00 FS
15	1		*FRONT TYRE RH	Serviceable	180.00 FS	*- FS
16	1		*FRONT TYRE RIM RH	Serviceable	120.00 FS	*- FS
17	1		*HUB CAP RH	Serviceable	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,798.23	1,570.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	782.06	342.50
Total Parts (\$\$)	3,016.17	1,227.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,400.00	300.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	220.00	30.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,350.00	400.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	120.00	20.00
5	TO REMOVE AND REPLACE CORPORATE STICKER	New	330.00	30.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
7	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
Gross Labour Cost (S\$)			3,810.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >