



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/TAN TAI KOON
	Reg No/Reg Date	SMP1019C / 11/09/201
	Date In/Mileage	22/07/2021/ 0
	Chassis No	MMBSTA13AKH002564
	Engine No	3A92UHX6862
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	22/07/2021/ 10:50	QUK	282 / Kevin Leong	13326			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								4080.00
REPLACE REAR BUMPER, BOOT, END PANEL, FLOOR ² PANEL, REAR LH FENDER, 7.5 x 450								3375
REAR LH HEADLAMP PANEL, BODY KIT & AFFECTED AREA								
REPAIR ON REAR RH FENDER								
E PNT98000								2800.00
PAINT WORK ON REAR BUMPER, BOOT, END PANEL, FLOOR PANEL, 6 x 350								2100
REAR LH TAILLAMP PANEL, BODY KIT & BOTH REAR FENDER								
E PNT88000								80 120.00
REMOVE & INSTALL REAR PARKING ASSIST								
E PNT88000								80.00
REMOVE & REPLACE REAR BODY KIT								
E PNT88000								240.00
REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR								
M SUNDRY								80.00
TO APPLY WINDSCREEN SEALANT								
E PNT88000								120 225.00
REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR								
E PNT88000								120.00
REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR								
A 13900099								450.00
REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR photo?								
E PNT88000								120.00
TO TRANSFER BOOT ATTACHMENTS TO NEW PANEL								
M SUNDRY								80 120.00
TO APPLY SEALANT ON AFFECTED AREA								
M SUNDRY								80 120.00
PERFORM RUST PREVENTION								
A 54900099								30.00
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
A WHEELALIGNMENTBP								7 120.00
To Conduct Computerize Full Wheel Alignment								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/TAN TAI KOON
	Reg No/Reg Date	SMP1019C / 11/09/201
	Date In/Mileage	22/07/2021/ 0
	Chassis No	MMBSTA13AKH002564
	Engine No	3A92UHX6862
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	22/07/2021/ 10:50	QUK	282 / Kevin Leong	13326			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								? 30.00
TO TRANSFER REAR LH RIM INCLUDING BALANCING								
M SUNDRY								? 260.00
TO SUPPLY REAR LH TYRE								
M SUNDRY								40.00
TO SUPPLY C & C EMBLEM								
M SUNDRY								50.00
TO SUPPLY REAR NUMBER PLATE WITH FRAME								
M SUNDRY								320.00
TO APPLY ZERTONA COATING ON AFFECTED AREA (sale agent)								
M SUNDRY								? 220.00
TO SUPPLY REVERSE SENSOR SET								
M SUNDRY								30.00
TO SUPPLY 'MIVIC' EMBLEM								
M SUNDRY								20 50.00
SUNDRIES								
M	LAMP ASSY, LICENSE PLATE	X			2.00	51.00	23.00	78.54
M	LAMP ASSY, COMB, RR LH	cr			1.00	337.00	23.00	259.49
M	LAMP ASSY, COMB, RR RH	?			1.00	337.00	23.00	259.49
M	REFLECTOR	?			1.00	23.00	23.00	17.71
M	REFLECTOR	?			1.00	23.00	23.00	17.71
M	FACE, RR BUMPER	des			1.00	751.00	23.00	578.27
M	BRACKET, RR BUMPER, LH	des			1.00	28.00	23.00	21.56
M	BRACKET, RR BUMPER, RH	des			1.00	28.00	23.00	21.56
M	PANEL, QTR, OTR LH	buc			1.00	759.00	23.00	584.43
M	PANEL, RR COMB LAMP HSG, LH	bt photo			1.00	60.00	23.00	46.20
M	FLOOR, RR	?			1.00	956.00	23.00	736.12
M	PANEL, RR END	bt			1.00	427.00	23.00	328.79
M	GLASS, RR WINDOW	X			1.00	544.00	23.00	418.88
M	STOPPER, WINDSHIELD GLASS	re			2.00	3.00	23.00	4.62
M	SPACER, RR WINDOW	re			3.00	9.00	23.00	20.79
M	PANEL, TRUNK LID	bt			1.00	795.00	23.00	612.15
M	HINGE, TRUNK LID, LH	X			1.00	203.00	23.00	156.31

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<table> <tr> <td>Cust No/Name</td><td>/TAN TAI KOON</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMP1019C / 11/09/201</td></tr> <tr> <td>Date In/Mileage</td><td>22/07/2021/ 0</td></tr> <tr> <td>Chassis No</td><td>MMBSTA13AKH002564</td></tr> <tr> <td>Engine No</td><td>3A92UHX6862</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>U01 / BK BLACK</td></tr> </table>	Cust No/Name	/TAN TAI KOON	Reg No/Reg Date	SMP1019C / 11/09/201	Date In/Mileage	22/07/2021/ 0	Chassis No	MMBSTA13AKH002564	Engine No	3A92UHX6862	Make/Model	MIT/19MY ATTRAGE 1.2 CVT	Colour/Trim	U01 / BK BLACK
Cust No/Name	/TAN TAI KOON														
Reg No/Reg Date	SMP1019C / 11/09/201														
Date In/Mileage	22/07/2021/ 0														
Chassis No	MMBSTA13AKH002564														
Engine No	3A92UHX6862														
Make/Model	MIT/19MY ATTRAGE 1.2 CVT														
Colour/Trim	U01 / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	22/07/2021/ 10:50	QUK	282 / Kevin Leong	13326			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	HINGE, TRUNK LID, RH				1.00	203.00	23.00	156.31
M	WEATHERSTRIP, TRUNK LID				1.00	157.00	23.00	120.89
M	STRIKER, TRUNK LID LATCH				1.00	20.00	23.00	15.40
M	LATCH, TRUNK LID				1.00	218.00	23.00	167.86
M	GARNISH, RR END PANEL				1.00	336.00	23.00	258.72
M	MARK, THREE-DIA				1.00	70.00	23.00	53.90
M	MARK, ATTRAGE				1.00	21.00	23.00	16.17
M	TRIM, RR END				1.00	66.00	23.00	50.82
M	BOARD, TRUNK ROOM FLOOR				1.00	195.00	23.00	150.15
M	CARPET, TRUNK ROOM				1.00	170.00	23.00	130.90
M	UNPAINTED BODYKITS				1.00	1643.00	20.00	1314.40
M	SHARK FIN ANTENNA, ATTRAGE GREY				1.00	123.00	20.00	98.40

LKK Auto Consultants hence notify

the Repairee of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: RASUL-Hp 90010060SURVEYOR SIGNATURE: [Signature]DATE: 22/07/21 @ 1420REMARKS: 14 days
Resy before paint
EXCESS: TRA

Confirm & accepted by

[Signature]

Nett	16,491.54
7% GST on	1154.41

Total Payable 17,645.95

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.