



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/TAN TAI KOON
	Reg No/Reg Date	SMP1019C / 11/09/201
	Date In/Mileage	22/07/2021/ 0
	Chassis No	MMBSTA13AKH002564
	Engine No	3A92UHX6862
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	22/07/2021/ 10:50	QUK	282 / Kevin Leong	13326			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, BOOT, END PANEL, FLOOR PANEL, REAR LH FENDER, REAR LH HEADLAMP PANEL, BODY KIT & AFFECTED AREA REPAIR ON REAR RH FENDER								4050.00
E PNT98000 PAINT WORK ON REAR BUMPER, BOOT, END PANEL, FLOOR PANEL, REAR LH TAILLAMP PANEL, BODY KIT & BOTH REAR FENDER								2800.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST								120.00
E PNT88000 REMOVE & REPLACE REAR BODY KIT								80.00
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN GLASS FOR FACILITATE REPAIR								240.00
M SUNDRY TO APPLY WINDSCREEN SEALANT								80.00
E PNT88000 REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR								225.00
E PNT88000 REMOVE & INSTALL REAR SEAT FOR FACILITATE REPAIR								120.00
A 13900099 REMOVE & INSTALL FUEL TANK FOR FACILITATE REPAIR								450.00
E PNT88000 TO TRANSFER BOOT ATTACHMENTS TO NEW PANEL								120.00
M SUNDRY TO APPLY SEALANT ON AFFECTED AREA								120.00
M SUNDRY PERFORM RUST PREVENTION								120.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								120.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment								120.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/TAN TAI KOON
	Reg No/Reg Date	SMP1019C / 11/09/201
	Date In/Mileage	22/07/2021/ 0
	Chassis No	MMBSTA13AKH002564
	Engine No	3A92UHX6862
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	22/07/2021/ 10:50	QUK	282 / Kevin Leong	13326			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								30.00
TO TRANSFER REAR LH RIM INCLUDING BALANCING								
M SUNDRY								260.00
TO SUPPLY REAR LH TYRE								
M SUNDRY								40.00
TO SUPPLY C & C EMBLEM								
M SUNDRY								50.00
TO SUPPLY REAR NUMBER PLATE WITH FRAME								
M SUNDRY								320.00
TO APPLY ZERTONA COATING ON AFFECTED AREA								
M SUNDRY								220.00
TO SUPPLY REVERSE SENSOR SET								
M SUNDRY								30.00
TO SUPPLY 'MIVIC' EMBLEM								
M SUNDRY								50.00
SUNDRIES								
M	LAMP ASSY,LICENSE PLATE				2.00	51.00	23.00	78.54
M	LAMP ASSY,COMB,RR LH				1.00	337.00	23.00	259.49
M	LAMP ASSY,COMB,RR RH				1.00	337.00	23.00	259.49
M	REFLECTOR				1.00	23.00	23.00	17.71
M	REFLECTOR				1.00	23.00	23.00	17.71
M	FACE,RR BUMPER				1.00	751.00	23.00	578.27
M	BRACKET,RR BUMPER,LH				1.00	28.00	23.00	21.56
M	BRACKET,RR BUMPER,RH				1.00	28.00	23.00	21.56
M	PANEL,QTR,OTR LH				1.00	759.00	23.00	584.43
M	PANEL,RR COMB LAMP HSG,LH				1.00	60.00	23.00	46.20
M	FLOOR,RR				1.00	956.00	23.00	736.12
M	PANEL,RR END				1.00	427.00	23.00	328.79
M	GLASS,RR WINDOW				1.00	544.00	23.00	418.88
M	STOPPER,WINDSHIELD GLASS				2.00	3.00	23.00	4.62
M	SPACER,RR WINDOW				3.00	9.00	23.00	20.79
M	PANEL,TRUNK LID				1.00	795.00	23.00	612.15
M	HINGE,TRUNK LID,LH				1.00	203.00	23.00	156.31

Confirm & accepted by

 Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/TAN TAI KOON
	Reg No/Reg Date	SMP1019C / 11/09/201
	Date In/Mileage	22/07/2021/ 0
	Chassis No	MMBSTA13AKH002564
	Engine No	3A92UHX6862
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	U01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	22/07/2021/ 10:50	QUK	282 / Kevin Leong	13326		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	HINGE,TRUNK LID,RH			1.00	203.00	23.00	156.31
M	WEATHERSTRIP,TRUNK LID			1.00	157.00	23.00	120.89
M	STRIKER,TRUNK LID LATCH			1.00	20.00	23.00	15.40
M	LATCH,TRUNK LID			1.00	218.00	23.00	167.86
M	GARNISH,RR END PANEL			1.00	336.00	23.00	258.72
M	MARK,THREE-DIA			1.00	70.00	23.00	53.90
M	MARK,ATTRAGE			1.00	21.00	23.00	16.17
M	TRIM,RR END			1.00	66.00	23.00	50.82
M	BOARD,TRUNK ROOM FLOOR			1.00	195.00	23.00	150.15
M	CARPET,TRUNK ROOM			1.00	170.00	23.00	130.90
M	UNPAINTED BODYKITS			1.00	1643.00	20.00	1314.40
M	SHARK FIN ANTENNA,ATTRAGE GREY			1.00	123.00	20.00	98.40

Confirm & accepted by

Net 16,491.54
 7% GST on 16491.54 1154.41
Total Payable 17,645.95

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.