

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/AIG21007838/Ura3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SCF1578A

at Workshop m/s Zoom

of

Insured: SMV 6297A

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$190k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

LTA 122480

Date / Time

Action / Instruction

Dep 25k.

Not 67520

Rear bumper 3886

head up 6521.58

10/8/11 1/5 @ 25.000 confirmed with 5/11

Veh No: SCF1578A Yr Regn: 25/11/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: mer Benz S320 c.c. 2996

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 79590 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD 2221622A 274476

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or off track

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45 R19

R: 275/40 R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 20/7/11

Survey held at

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 22/7/11

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear & n/s u/c & Bty.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

) S + RS. SI

) Photos

) Others

TOTAL

Like: Teslin

Not Attached



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

WHL

Car Number: SCF1518A

Model : Mercedes-Benz

Damaged Area: (Rear RH, Front Centre, Frt & Rear Left Undercarriage)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

d/s \$ 25,000

22/7/21

Take photo after repair
12 days.

Parts / Material :

1	Rear Bumper	Dis	2452.22	\$	2,695.80	✓
2	Rear Bumper Bracket RH	11		\$	176.40	X
3	Rear Bumper Side Retainer RH	Che		\$	116.20	✓
4	Rear Bumper Side Mount RH	11		\$	233.00	X
5	Rear air ventols	Che	112.50	\$	158.60	✓
6	Rear bumper reinforcement	Beut		\$	490.00	✓
7	Rear Bumper Angle Sensor RH	Shells		\$	228.00	✓
8	Reverse Sensor Bracket (Set)	11		\$	96.00	X
9	Rear Bumper Chrome RH	Che	118.48	\$	155.40	✓
10	Rear Bumper Clips (Set)	11		\$	60.00	✓
11	Rear Taillamps RH	Che	1032.20	\$	1,865.70	✓
12	Rear Fender RH	Body		\$	2,595.80	✓
13	Rear exhaust heatshieldols	Dis		\$	486.70	✓
14	Rear Fender Inner Trim Clips (Set)	11		\$	60.00	X
15	Rear Fender Inner Shield RH	Torn		\$	286.40	✓
16	Rear Fender Inner Shield Clips (Set)	11		\$	60.00	✓
17	Rear Fuel Tank Lid	Garnish	Che	\$	296.50	✓
18	Rear Door RH	11		\$	3,648.00	X
19	Rear Door Weather Strip RH	11		\$	398.60	X
20	Rear Door Moulding RH	11		\$	286.20	X
21	Rear Wheel Rim RH	11/Beut	980	\$	1,186.70	✓
22	Rear Wheel Rim LH	11/Beut	980	\$	1,186.70	✓
23	Rear Lower Arm @ SGD 548.20	11		\$	1,096.40	X
24	Rear Knuckle Arm @ SGD 670.50	Beut		\$	1,341.00	✓
25	Rear Hub Bearing @ SGD 386.70	11		\$	773.40	✓
26	Rear Upper Arm @ SGD 320.80	11		\$	641.60	X
27	Rear floor panel inner side bracket	Che		\$	575.20	✓
28	Rear floor side panel ols	crumpled		\$	701.60	✓
29	Front Bumper	de/waped	2566.21	\$	2,870.60	✓
30	Front Bumper Side Mount @ SGD 226.40	11		\$	452.80	X
31	Front Bumper Based Garnish	Re		\$	98.00	✓
32	Front Bumper Bracket @ SGD 264.00	11		\$	528.00	X
33	Front Bumper Side Retainer @ SGD 324.60	11		\$	649.20	X
34	Front Bumper Clips (Set)	11		\$	60.00	✓
35	Front Bonnet	11/Beut	3350.60	\$	3,350.60	✓
36	Front Bonnet Lock Level	11		\$	237.00	X
37	Front Bonnet Lock Spring @ SGD 98.50	11		\$	197.00	X
38	Front Bonnet Hinge @ SGD 242.40	11		\$	484.80	X
39	Front Bonnet Star Logo	11	145.00	\$	228.60	✓
40	Front Headlamp @ SGD 3896.70	Che		\$	7,793.40	✓
41	Front Headlamp Control Unit @ SGD 1539.20	11		\$	3,078.40	X
42	Front Support Panel Top	11		\$	1,546.20	X
43	Front Support Panel Top Garnish	11		\$	426.50	X
44	Front Support Panel Top Garnish Clips (Set)	11		\$	60.00	X
45	Front Radiator Grille Assy	Che	1025	\$	1,486.70	✓
46	Front Wheel Rim RH	11/Beut	980.00	\$	1,186.70	✓

47 Front Shock Absorber LH 11
 48 Front Knuckle Arm LH 304 1355
 49 Front Hub Bearing LH 292 485.00
 50 Front Lower Arm LH 11
 51 Front Control Arm LH 11
 52 Front Anti Roll Bar 11
 53 Front Anti Roll Bar Linkage LH 11

\$ 3,190.00 X
 \$ 1,078.60 X
 \$ 1,092.00 X
 \$ 814.60 X
 \$ 649.20 X
 \$ 468.70 X
 \$ 76.00 X

Parts : \$
 Less Parts 10% : \$
 Total Parts : \$

Special Net Items :

Rear Fender Sealant 11
 2pcs Rear Tyre @ SGD 580.00 500
 1pc Front Tyre LH 500
 Front Number Plate W/Garnish 304
 Rear Windscreen Glass Inner Seal s 11
 Rear Windscreen Glass Sealant 11

\$ 80.00 X
 \$ 1,160.00 X
 \$ 580.00 X
 \$ 65.00 40
 \$ 150.00 40
 \$ 80.00 40

Total S/N Parts : \$ 2,115.00

Labour :

To Remove, Repair & Renew Rear Affected Accident Areas
 To Putty, Spray Paint on Affected Accident Areas
 To Check & Re-Connect all electrical wiring
 To Remove & Install Rear Bootlid Components Trim & Garnish
 To Remove & Install Rear Fenders Trim, Garnish, Spare Tyre Compartment
 To Conduct All Wheel Alignment
 To Remove & Install Front Left Undercarriage Components
 To Remove & Install Rear Undercarriage Components
 To Re-position & Align Reverse Sensor
 To Re-programme & Re-set Star Diagnostics
 To Conduct Water Leakage Test
 To Rust Proof Affected Areas

\$ 1,800.00 1200
 \$ 1,400.00 1200
 \$ 50.00 30
 \$ 11 150.00 X
 \$ 150.00 100
 \$ 150.00 80
 \$ 250.00 120
 \$ 500.00 240
 \$ 120.00 50
 \$ 450.00 100
 \$ 11 150.00 X
 \$ 200.00 90

Total Labour : \$ 5,370.00

TOTAL PARTS : \$
 TOTAL SPECIAL NET ITEM : \$
 TOTAL LABOUR : \$
 TOTAL REPAIR COST : \$

DATE OF SURVEY / INSPECTED:
 RECOMMENDED PART BY PART / LUMP SUM :
 RECOMMENDED NUMBER OF DAYS :
 SURVEY BY / SURVEYOR FIRM :
 RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :
 FINALISED AMOUNT :

7-31268.01
 102
 P-28141-20
 S.N -120
 1-3210

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 696B

Vehicle Details

Vehicle No.: SCF1518A
Vehicle to be Exported: No
Intended Deregistration Date: 22 Jul 2021
Vehicle Make: MERCEDES BENZ
Vehicle Model: S320 EXECUTIVE
Primary Colour: Silver
Manufacturing Year: 2016
Engine No.: 27682430412669
Chassis No.: WDD2221622A274476
Maximum Power Output: 200.0 kW (268 bhp)
Open Market Value: \$84,054.00
Original Registration Date: 25 Nov 2016
First Registration Date: 25 Nov 2016
Transfer Count: 0
Actual ARF Paid: \$123,298.00 61649

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 24 Nov 2026
PARF Rebate Amount: \$92,473.00

Intended COE Rebate Details

COE Expiry Date: 24 Nov 2026
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$56,206.00
COE Rebate Amount: \$30,007.00
Total Rebate Amount: \$122,480.00

The information contained herein is correct as at 22 Jul 2021

OK

SAVE
UP TO **\$600**

On Your Car Insurance Renewal! [Get Cheaper Quotes](#)
Compare from 12 insurers with our trusted partner. Hassle Free!



Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Approval Case Up To 99%, High Trade In Price



\$2,888 Drive away, Bank Loan
@ 1.88% and 100% In House
Financing @ 3.28%.
5G Motors StarAd

KA-HUP

HOTLINE: 6741 9997

[view our cars](#)

**VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND**

Browse by Category

Sort by Date Posted 20 results/page

11 vehicles

Mercedes-Benz s320

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mercedes-Benz	S320	Any	Any	2016	Any	Any	Any	Available
	Mercedes-Benz	S-Class S320L	\$193,800	\$26,320 /yr	17-May-2016	2,996 cc	53,000 km	Luxury	Available
Promo 1.88% Bank Loan Interest Rate. R19 Model, C&C Unit. Agent Service By C&C. Black With Black Interior. Very Well Maintained, Vi... Pure Motors Pte Ltd Posted: 21-Jul-2021 Tags: 2016 Mercedes-Benz S320L, Mercedes-Benz S320L, Mercedes-Benz, S320L									
	Mercedes-Benz	S-Class S320L	\$213,888	\$29,760 /yr	09-Sep-2016	2,996 cc	128,000 km	Luxury	Available
Nice! Very Well Kept, Serious Buyer Only. Thanks! Posted: 19-Jul-2021 Tags: 2016 Mercedes-Benz S320L, Mercedes-Benz S320L, Mercedes-Benz, S320L DIRECT OWNER									
	Mercedes-Benz	S-Class S320L	\$197,800	\$26,800 /yr	09-Jun-2016	2,996 cc	69,954 km	Luxury	Available
1 Owner, Low Mileage Unit. High Loan With Low-Interest Rate Package Available! Contact Our Sales Consultant To Arrange For A Viewing! Posted: 18-Jul-2021 Tags: 2016 Mercedes-Benz S320L, Mercedes-Benz S320L, Mercedes-Benz, S320L									
	Mercedes-Benz	S-Class S320L	\$208,800	\$26,950 /yr	26-Oct-2016	2,996 cc	80,000 km	Luxury	Available
1 Owner! Agent (C&C) Unit! Fully Serviced By Agent! Flexible Loan With High Approval Rate! 100% Loan Available! Call Us Now To Arra... Hamilton Autohub Pte Ltd Posted: 17-Jul-2021 Tags: 2016 Mercedes-Benz S320L, Mercedes-Benz S320L, Mercedes-Benz, S320L									
	Good Condition Used Mercedes Benz 18" Rims USED 4 pcs Original Mercedes 18" Rims, fitment for all Mercedes PCD 5x112. Full Installation, Balancing & Nitrogen fill. More info about this product								
	Mercedes-Benz	S-Class S320L	\$206,800	\$26,590 /yr	25-Oct-2016	2,996 cc	53,000 km	Luxury	Available
Agent (C&C) Unit! Fully Serviced By Agent! Black With Beige Interiors! Luxury And Spacious Vehicle. Well Maintained! Low Mileage Done... Starise Automobile Posted: 16-Jul-2021 Tags: 2016 Mercedes-Benz S320L, Mercedes-Benz S320L, Mercedes-Benz, S320L PREMIUM AD									
	Mercedes-Benz	S-Class S320L	\$198,800	\$26,010 /yr	16-Aug-2016	2,996 cc	92,000 km	Luxury	Available
1 Owner, Full Maintenance And Service Record By C&C, Flexible Loan With High Approval Rate, Promo 1.88% Bank Loan Interest Rate.... Posted: 13-Jul-2021 Tags: 2016 Mercedes-Benz S320L, Mercedes-Benz S320L, Mercedes-Benz, S320L									
	Mercedes-Benz	S-Class S320L	\$194,800	\$26,400 /yr	25-May-2016	2,996 cc	102,544 km	Luxury	Available
1 Owner, Fully C&C Maintained. High Loan With Low Interest Rate, High Trade In. Contact Our Sales Consultant To Arrange For A Viewi... Posted: 11-Jul-2021 Tags: 2016 Mercedes-Benz S320L, Mercedes-Benz S320L, Mercedes-Benz, S320L									

[Compare](#)

TECHNEAT PTE LTD
8 Kaki Bukit Avenue 4
(Enter by Gate 2)
#03-38/39/40
Premier@Kaki Bukit
Singapore 415875

Tel : (65) 6384 1996
Fax : (65) 6384 1996
Hotline : (65) 9691 0887
Email: techneatcarcare@yahoo.com.sg
Business Hour : 9am to 7pm(Mon to Sat)

Service - Repair - Rim - Tyres - Battery - Balancing & Alignment

Work Order: SCF 1518 A
Date 22.7.21 17:00

Mercedes-Benz : 222 (S Class 2013-) : Rear Wheel Drive : Air Suspension Europe version/USA (W/V/X)

Front : Left

Actual	Before	Specified Range
-0°29'		-0°52' -0°08'
8°50'		
0°14'		0°02' 0°12'
8°09'		
7°41'		
		-1°59' -0°59'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-3°42'		-0°52' -0°08'
8°44'		
-0°31'		0°02' 0°12'
13°14'		
9°32'		
		-1°59' -0°59'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
3°14'		-0°24' 0°24'
0°06'		-0°30' 0°30'
-5°05'		
-0°17'		0°04' 0°25'

Rear : Left

Actual	Before	Specified Range
-4°16'		-2°22' -1°22'
-0°25'		0°05' 0°20'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-2°53'		-2°22' -1°22'
1°06'		0°05' 0°20'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-1°23'		-0°30' 0°30'
0°41'		0°18' 0°32'
-0°45'		-0°08' 0°08'

8 Kaki Bukit Avenue 4
(Enter by Gate 2)
#03-38/39/40
Premier@Kaki Bukit
Singapore 415875

Tel : (65) 6384 1996
Fax : (65) 6384 1996
Hotline : (65) 9691 0887
Email: techneatcarcare@yahoo.com.sg
Business Hour : 9am to 7pm(Mon to Sat)

Service - Repair - Rim - Tyres - Battery - Balancing & Alignment

Work Order: SCF1518A
Date 5.8.21 13:50

Mercedes-Benz : 222 (S Class 2013-) : Rear Wheel Drive : Air Suspension Europe version/USA (W/V/X)

Front : Left

Actual	Before	Specified Range
-0°48'	-0°57'	-0°52' -0°08'
8°59'	8°59'	
0°11'	0°03'	0°02' 0°12'
7°54'	8°04'	
7°06'	7°06'	
		-1°59' -0°59'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°46'	-0°52'	-0°52' -0°08'
8°44'	8°44'	
0°09'	-0°10'	0°02' 0°12'
11°01'	11°07'	
10°15'	10°15'	
		-1°59' -0°59'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°01'	-0°06'	-0°24' 0°24'
0°15'	0°15'	-0°30' 0°30'
-3°07'	-3°03'	
0°19'	-0°07'	0°04' 0°25'

Rear : Left

Actual	Before	Specified Range
-1°54'	-1°54'	-2°22' -1°22'
-0°07'	-0°41'	0°05' 0°20'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-2°10'	-2°06'	-2°22' -1°22'
0°12'	1°04'	0°05' 0°20'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
0°17'	0°12'	-0°30' 0°30'
0°05'	0°23'	0°18' 0°32'
-0°10'	-0°52'	-0°08' 0°08'