



ASSESSMENT FOR REPAIR : FBQ6280E

HONDA ADV150 ABS CVT

COE EXPIRY : 15 Nov 2029

Lump Sum / Part by Part

Qty	Description	Repairer's Estimate	1st Survey	Repair Survey	Final Survey
1	FRONT TOP RH COWLING	64.20			
1	RH FOG LIGHT	321.00			
1	MIRROR	80.26			
1	RH BRAKE LEVER	48.16			
1	BAR END	32.10			
1	FRONT FENDER	224.70			
1	FORK (SET)	1,284.00			
1	RH SIGNAL LIGHT (FRONT)	112.36			
1	FRONT BOTTOM RH COWLING	385.20			
1	RH FOOTMAT STAY	160.50			
1	RH FOOTMAT COVER	192.60			
1	PILLION FOOTREST PEG	48.16			
1	REAR MUDGUARD	224.70			
1	HANDLEBAR	160.50			
1	LH TRANSMISSION COVER	288.90			
1	LH AIRBOX COVER	128.40			
1	EXHAUST MUFFLER COVER	256.80			
1	EXHAUST PROTECTOR	192.60			
1	EXHAUST CAP	96.30			
1	RH REAR COWLING	256.30			
1	METAL RACK FOR BOX (HEAVY DUTY)	434.00			

4,991.74

Special Nett Items

STEERING CONE & BEARING	120.00			
FRONT FORK ALIGNMENT	220.00			
WHEEL ALIGNMENT	120.00			
FRAME ALIGNMENT	200.00			
BOX GIVI	481.50			

1,141.50

Total Parts

6,133.24

Labour Charges

1	Workmanship to renew damage parts & areas	350.00
		<u>350.00</u>

Total Parts & Labours Concluded

6,483.24

SANFU MOTOR PTE LTD

Company Reg No.: 200612487G

1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883

Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010

Email: sanfumotor0243@gmail.com