

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	GREAT AMERICA	N INSURANCE COMPANY	Ref:	CS/GAI21007842/T1vf3e2	
	3 TEMASEK AVEN #16-01 CENTENNI SINGAPORE 0391	IAL TOWER	Date:	30/07/2021	
			Code:	GAI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBC 4873G	Veh. Inspected	SHD 3380S	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CLMOMVC000004043	Excess (\$)	0.00	
	Assign From	SHERY WONG	Assign Date	22/07/2021	
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI 140	c.c	1685	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	KMHLB41UMGU093306	Colour	BLUE	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
	L/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
	R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
	L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	20/07/2021	Inspection Date	22/07/2021	
	Survey held at	COMFORTDELGRO ENGINEER	RING PTE LTD		
		59 LOYANG DRIVE SINGAPORE 508969			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				