

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

Affiliated to Federation Internationale Des Experts En Automobile					
	AIG ASIA PACIFIC	INSURANCE PTE LTD	Ref:	CS3/AIG21000947/Gvf3e2-1	
	78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120		Date:	26/07/2021	
	ATTN: JEREMY GO	ЭН	Code:	AIG	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMN 982M	Veh. Inspected	SMF 6649D	
	Policy No.	1900122326	Coverage (\$)	0.00	
	Claim No.	9095418535SG	Excess (\$)	0.00	
	Assign From	JEREMY GOH	Assign Date	22/07/2021	
2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ C 200	c.c	1796	
	Engine No.	HIDDEN	Year of Reg.	2009	
	Chassis No.	WDD2040412A258168	Colour	BLACK	
	Odometer	197913 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
	L/H Front Tyre	225/45 R17	BRIDGESTONE	6 mm	
	R/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
	L/H Rear Tyre	225/45 R17	BRIDGESTONE	6 mm	
4.	l. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	16/01/2021	Inspection Date	25/01/2021	
	Survey held at	No. 68 Kaki Bukit Avenue 6, #01	-09 Ark		
	Repairer	Repairer ELITES PERFORMANCE			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				