

DING AUTO PTE LTD

Blk 176 #04-06

Sin Ming Drive (Sin Ming Autocare)

Singapore 575721

Tel: 83636141

Fax: 6452 0614

Vehicle: SJZ8544P

Model: SUZUKI SWIFT 1.5GL AT

Chassis: JSAEZC21S00566544

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYOR MARKING
1	FRONT BUMPER COVER <i>575</i> <i>Bu/Car</i>	1	\$ 690.95	15%	\$ 587.30	✓
2	FRONT BUMPER CENTRE GRILLE <i>Sm</i>	1	\$ 76.95	15%	\$ 65.40	X
3	FRONT BUMPER LOWER GRILLE <i>Sm</i>	1	\$ 80.65	15%	\$ 68.55	X
4	FRONT BUMPER RETAINER RHS <i>Dis</i>	1	\$ 31.15	15%	\$ 26.47	✓
5	FRONT BUMPER RETAINER LHS <i>Sm</i>	1	\$ 31.15	15%	\$ 26.47	X
6	FRONT BUMPER LOWER GARNISH RHS <i>Pol/LH</i>	1	\$ 16.55	15%	\$ 14.06	✓
7	FRONT BUMPER LOWER GARNISH LHS <i>Sm</i>	1	\$ 16.55	15%	\$ 14.06	X
8	BUMPER TOWING CAP <i>Pol</i>	1	\$ 29.60	15%	\$ 25.16	✓
9	FRONT REINFORCEMENT <i>By</i>	1	\$ 190.05	15%	\$ 161.54	✓
10	FRONT TOP SUPPORT PANEL <i>R</i>	1	\$ 79.50	15%	\$ 67.57	X
11	FRONT LOWER SUPPORT PANEL <i>R</i>	1	\$ 95.90	15%	\$ 81.51	X
12	FRONT LOWER TRIM PANEL <i>R</i>	1	\$ 163.85	15%	\$ 139.27	X
13	ENGINE LOWER COVER RH <i>Sm</i>	1	\$ 59.70	15%	\$ 50.74	X
14	ENGINE LOWER COVER LH <i>Sm</i>	1	\$ 59.70	15%	\$ 50.74	X
15	HEADLAMP ASSY RH <i>386</i> <i>mgcna</i>	1	\$ 437.10	15%	\$ 371.53	✓
16	HEADLAMP ASSY LH <i>Sm</i>	1	\$ 437.10	15%	\$ 371.53	X
17	CENTRE GRILLE BADGE <i>Sm</i>	1	\$ 29.85	15%	\$ 25.37	X
TOTAL:					\$ 2,147.27	

Not Notation
U/Sup @ 1450/r
Resurvey After Paint
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	SPECIAL NETT	QTY	PRICE	SURVEYOR MARKING
1	FRONT BUMPER & FENDER INNER SHIELD BRACKETS/CLIPS	<i>nn</i> 1	\$ 100.00	<i>X</i>
2	CAR NUMBER PLATE & FRAME	<i>CPM</i> 1	\$ 50.00	<i>455n</i>
	SPECIAL NETT		\$ 150.00	

	LABOUR	PRICE	SURVEYOR MARKING
1	PANEL BEATING AND STRAIGHTEN ACCIDENT AREAS	\$ 800.00	<i>3001</i>
2	SPRAY PAINT - FRT BUMPER, FENDER RH, FENDER LH & BONNET(INNER/OUTER)	\$ 1,500.00	<i>4001</i>
3	REMOVE & REFIT BUMPER COMPONENTS	<i>nn</i> \$ 80.00	<i>X</i>
4	REMOVE & REFIT HEADLAMP RH/LH	\$ 120.00	<i>3 201</i>
5	ALIGN HEADLAMP AND TEST WIRING	\$ 60.00	<i>1</i>
	TOTAL :	\$ 2,560.00	

PARTS	\$ 2,147.27	
LABOUR	\$ 2,560.00	
SPECIAL NETT	\$ 150.00	
TOTAL	\$ 4,857.27	
GST 7%	\$ 340.01	
FINAL TOTAL	\$ 5,197.28	