

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMJ7346A
 at Workshop m/s Asia motorsports
 of _____
 Insured: SHA2731K
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$55k.
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: 792E

Veh No: SMJ7346A Yr Regn: 73/11/10
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA/
 Make: mer Benz C200 c.c. 1796
 Colour: black A/C: Insured / Std / NI / NA
 Sp. Reading: 152926 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WDD2040412A341430
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

19/7/14

D.O.I.

22/7/14

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

we until 30-4-2028 LTA \$27522

2/8/14 1/5 @ 5600 confirmed with AH Long

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL

* with HSI 145704
not Author

21/7/21

L/5 \$5600 S. Langs
Telephle After Agmt

SMJ7346A Mercedes Benz C200

No.	Qty	Parts Description	Parts Price
1	1	Rear bumper assy <i>Dis</i>	\$ 1,321.60 ✓
2	1	Rear bumper tow hood cover <i>clw hugu</i>	\$ 78.50 X
3	1	Rear bumper centre chrome moulding <i>neu</i>	\$ 125.20 ✓
4	1	Rear bumper right side chrome moulding <i>neu</i>	\$ 112.30 ✓
5	1	Rear bumper left side chrome moulding <i>neu</i>	\$ 112.30 ✓
6	1	Rear bumper center bracket <i>ns</i>	\$ 152.70 X
7	1	Rear bumper left side retainer <i>one</i>	\$ 88.10 ✓
8	1	Rear bumper right side retainer <i>one</i>	\$ 88.10 ✓
9	1	Rear bumper left bracket <i>one</i>	\$ 77.50 ✓
10	1	Rear bumper right bracket <i>11</i>	\$ 77.50 X
11	1	Rear bumper reinforcement <i>22 615.00</i>	\$ 650.80 ✓
12	1	Rear left taillamp assy <i>one 585.21</i>	\$ 643.50 ✓
13	1	Rear right taillamp assy <i>11</i>	\$ 643.50 X
14	1	Rear left taillamp top garnish <i>11</i>	\$ 75.10 X
15	1	Rear right taillamp top garnish <i>11</i>	\$ 75.10 X
16	1	Rear end lower panel (inner) <i>ns</i>	\$ 863.90 X
17	1	Rear end lower panel (outer) <i>30.500</i>	\$ 843.80 ✓
18	1	Rear end lower panel top garnish <i>7m1</i>	\$ 127.50 ✓
19	1	Rear exhaust muffler complete assy <i>11</i>	\$ 1,878.90 X
20	1	Rear exhaust muffler upper heat shield <i>11</i>	\$ 125.20 X
21	1	Rear exhaust muffler lower heat shield <i>11</i>	\$ 126.40 X
22	1	Rear bootlid assy <i>1</i>	\$ 1,655.10 X
23	1	Rear bootlid centre logo <i>neu 60</i>	\$ 151.50 ✓
24	1	Rear bootlid 'kompressor' emblem <i>neu 75</i>	\$ 117.50 ✓
25	1	Rear bootlid 'C200' emblem <i>neu 62</i>	\$ 124.20 ✓
26	1	Rear bootlid lock mechanism <i>11</i>	\$ 280.10 X
27	1	Rear bootlid lock catch <i>11</i>	\$ 68.80 X
28	1	Rear bootlid weatherstrip <i>7m1 248.21</i>	\$ 298.40 ✓
29	2	Rear bootlid number plate lamps <i>11</i>	\$ 180.30 X
30	1	Rear floor panel <i>well fibre one 615</i>	\$ 1,290.90 ✓
31	1	Rear bootlid top lip <i>3m</i>	\$ 650.10 X
			\$ 13,104.40
		less 10%	\$ 1,310.44
			\$ 11,793.96

SMJ7346A Mercedes Benz C200

Qty. Parts Description			Estimated Parts Price	
<u>Special Nett Items</u>				
1	10	Rear bumper clips <i>all</i>	S	80.00 <i>50</i>
2	1	Rear view camera <i>all</i>	S	500.00 <i>X</i>
3	1	Rear floor panel insulator pad <i>all</i>	S	180.00 <i>X</i>
4	1	Rear floor panel sealant <i>all</i>	S	150.00 <i>60</i>
5	4	Rear bumper reverse sensor <i>shut</i>	S	1,400.00 <i>200</i>
6	1	Rear no plate with garnish <i>all</i>	S	100.00 <i>X</i>
7	1	Rear end lower panel sealant (inner) <i>all</i>	S	150.00 <i>50</i>
8	1	Rear end lower panel sealant (outer) <i>all</i>	S	150.00 <i>X</i>
9	4	Rear end panel top garnish clips <i>all</i>	S	30.00 <i>X</i>
10	1	Rear bootlid top lip sealant <i>all</i>	S	80.00 <i>X</i>
			S	<u>2,820.00</u>
Total parts			\$	14,613.96

SMJ7346A Mercedes Benz C200

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts including floor panel.	\$ 1,200.00	900
2	To putty and spray painting rear portion.	\$ 1,200.00	1000
3	To check rear lighting and wiring.	\$ 50.00	30
4	To remove and install rear bootlid lock mechanism.	\$ 80.00	X
5	To remove and install rear exhaust muffler assy.	\$ 120.00	X
6	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 150.00	80
7	To apply anti rust proofing to rear affected area.	\$ 140.00	50
8	To remove and install rear bumper reverse sensor.	\$ 80.00	50
9	To remove and install rear view camera.	\$ 80.00	X
10	Towing service.	\$ 100.00	X
Total labour :		\$ 3,200.00	

Total parts : \$ 14,613.96

Total labour : \$ 3,200.00

Total repair cost : \$ 17,813.96

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-558682
102
P-464113
S.N-360-00
L 2/10.00
7/11.13