



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL
64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Ref: CS3/III21007046/R1qf3 -1

Date: 25/06/2021

Code: III2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLV 9651D	Veh. Inspected	SJJ 1376M
Policy No.	D21MFL0000447	Coverage (\$)	0.00
Claim No.	MFL2021D0003001	Excess (\$)	0.00
Assign From	BHUVANESWARI	Assign Date	25/06/2021

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	22/06/2021	Inspection Date	28/06/2021
Survey held at	A-TEC MOTORZ PTE LTD 39 WOODLAND CLOSE #02-43 MEGA @WOODLAND SINGAPORE 737856		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.