

Kenneth

ASSIGNMENT

From:

Estimated Cost:

Date:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ - RS. SI

Fees

Others

TOTAL

Veh No:

S14B9755R Yr Regn: 07, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Pro S c.c. 1798

Colour

M. P. White / Red AC: Insured / Std / NI / NA

Sp. Reading

100168 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDK B3FU 403091190

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

9 mm

Rear

R/Bal.

9 mm

L/Bal.

9 mm

L/Bal.

9 mm

D.O.A.

14/7/21

D.O.I.

21/7/2021

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Fnt

The U/C / Chassis frame / Body Structure affected due to collision.

Trans-cab Auto Services Pte Ltd

AAD2107-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9755R

Not Authored
Peny Bepaint

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

21 JUL 2021

SHB9755R

JTDKB3FU403091190

TOYOTA

PRIUS GEN 4

14/07/2021

China.

14/07/2020

PART	LIST	
1 COVER, FRONT BUMPER	\$ Bu	521.00 ✓
1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$ Sn	110.50 X
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$ R	716.60 X
1 ABSORBER, FRONT BUMPER ENERGY	\$ Sn	80.20 X
1 SUPPORT, FRONT BUMPER SIDE, RH	\$ Sn	80.10 X
1 EXTENSION, FRONT BUMPER, RH	\$ Sn	120.10 X
1 UNIT ASSY, HEADLAMP, RH	\$ Sn	2,637.60 X
1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$ Sn	3,772.50 X
1 FENDER SUB-ASSY, FRONT RH	\$ R	977.80 ✓
1 LINER, FRONT FENDER, RH	\$ Sn	202.50 X
1 EMBLEM, SIDE PANEL	\$ R	54.60 ✓
1 MOULDING, FRONT BUMPER SIDE, RH	\$ Sn	95.6 X
TOTAL	\$	9,369.10
25%	\$	2,342.28
	\$	7,026.83

Special Nett

1SET BUMPER CLIP FRT	\$ R	95.00 50511
1 FRONT FENDER CLIP	\$ R	60.00 X
1SET CLIP, FRONT FENDER LINER	\$ R	85.00 X
1SET FRNT BUMPER RETAINER CLIP	\$ R	85.00 X
TOTAL	\$	325.00

TOTAL PARTS \$ 7,351.83

LABOUR

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ R 380.00 X

Trans-cab Auto Services Pte Ltd**AAD2107-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9755R

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	3001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	380.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	301
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	4401
To reinstall rear bumper parking sensor.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	101
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	220.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	380.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHB9755R

AAD2107-

To conduct and perform a comprehensive vehicle diagnostic check
and reset vehicle warning indicators.

\$ 380.00 X
TOTAL \$ 8,670.00

Over All Total \$ 16,021.83

(PART-BY-PART) Repair Days

25 DAYS
2 day,

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: