

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21007862/KGS3Q2
Date: 18/11/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	SJX2252G	Insured Vehicle No :	SLK7263L
Date of Loss:	15/07/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0003055

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX2252G		
Make & Model:	MITSUBISHI LANCER, 1.6 EX SPORTS (M)	Engine No:	4A910126361
Reg. Date:	26/05/2010 (Man. Year: 2009)	Chassis No:	JMYSRCY2AAU000387
Colour:	Metallic Blue	Odometer:	164838 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,575.50	1,104.00	471.50	29.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	915.00	775.00	140.00	15.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,490.50	1,879.00	611.50	24.55
Approved Total (Overridden) (S\$)		1,500.00		

(S\$)	2,490.50	1,500.00	990.50	39.77
+ GST 7.00/7.00% (S\$)	174.34	105.00	69.34	39.77
Nett Amount (S\$)	2,664.84	1,605.00	1,059.84	39.77
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 22/07/2021

Date Inspected: 02/08/2021

Estimated Period of Repair: 4.0 days

Inspected At:

S & H Motor Pte Ltd (Sin Ming)
 160 Sin Ming Drive #07-02, Sin Ming AutoCity
 Singapore 575722

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Nov 2021)
Parts:	143	MITSUBISHI LANCER 1.6 EX SPORTS (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX2252G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT DOOR (WCP)	Bent	580.00 F	*580.00 F
2	1		*RH FRONT FENDER (WCP)	Bent	380.00 F	*380.00 F
3	1		*RH FRONT DOOR SIDE MIRROR BASE (WCP)	Serviceable	320.00 F	*- F
4	1		*RH FRONT DOOR SIDE MIRROR COVER (WCP)	Repair	90.00 F	*- F
					Sub Total (S\$)	1,370.00
					+ Margin on L,N Items 15.00/15.00% (S\$)	205.50
					Total Parts (S\$)	1,575.50
						960.00
						1,104.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE DAMAGED PARTS ,TO REPLACE RH FRONT DOOR ,RH FRONT FENDER,TO REMOVE AND REFIT DOOR TRIM,LOCK,WINDOW ,TO REPLACE DAMAGED PARTS AND ADJUST BODY PANEL ALIGNMENT	New	350.00	300.00
2	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY	New	15.00	15.00
3	TO SPRAY PAINT AFFECTED RH SIDE AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND MATERIAL	New	450.00	400.00
4	TO APPLY ANTI-CORROSION TUFF-KOTE	New	100.00	60.00
Gross Labour Cost (S\$)			915.00	775.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >