

Height Matters
3 West Coast Walk #13-06
The Parc Condominium
Singapore 127140

File No : SH/2021/067/07/007/TP
Date : 27-July-2021

Estimated cost of repair for vehicle no : SJX2252G Mitsubishi Lancer
Accident involving vehicle no: SJX2252G & SLK7263L on 15.07.2021

Description	Quantity	Cost Price
RH front door	1	\$ 580.00 ✓
RH front fender	1	\$ 380.00 ✓
RH front door side mirror base	1	\$ 320.00 X
RH front door side mirror cover	1	\$ 90.00 X
		\$ 1,370.00
	Add 15%	\$ 205.50
		\$ 1,575.50

To remove damaged parts, to replace RH front door, RH front fender, to remove and refit door trim, lock, window, to replace damaged parts and adjust body panel alignment

\$ 350.00 300

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality

\$ 15.00 ✓

To spray paint affected RH side and inner damaged portion inclusive of preparatory works and material

\$ 450.00 400

To apply anti-corrosion Tuff-Kote

\$ 100.00 60

\$ 2,490.50

T/Party: India International Insurance Pte Ltd

Not Authorised
L1Pm &
Resurvey After Paint
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: