

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : QBE INSURANCE (SINGAPORE) PTE LTD
1 RAFFLES QUAY
#29-10 SOUTH TOWER
SINGAPORE 048583
TEL: 62246633 FAX: 65345356
ATTN: Motor Claim Department

Estimate No: EST2100191
Date: 16 Jul 2021

Veh Reg No: SKR2843X
Make/Model: TOYOTA VIOS J GRADE MT
Chasis No: MHFBT9F3306029824
Reg. Date: 29/01/2015
Your Ref No: SLK6599A

Claim Type: Third Party
Accident Date: 15/07/2021
TP Veh Reg No: SLK6599A

Ashes

Estimate Repair Cost to Vehicle No :SKR2843X

Quantity	Description	List Price	Amount
		SS	SS
List Price			
1	1 PC BOOT LID <i>Dented</i>	765.80	✓
2	1 PC BOOT LID GARNISH <i>new</i>	161.60	+
3	1 PC BOOT LID LOGO	63.80	✓
4	1 PC BOOT LID "VIOS" EMBLEM <i>3 Mer</i>	43.60	✓
5	1 PC BOOT LID LOCK <i>Dented</i>	195.90	✓
6	1 PC BOOT LID LOCK CHECKER <i>new</i>	39.90	+
7	1 PC BOOT LID RUBBER <i>cut</i>	166.40	2
8	1 PC REAR PANEL <i>Dented</i>	620.10	2
9	1 PC REAR PANEL TRIM <i>Crackd</i>	231.10	2
10	1 PC REAR FENDER INNER TRIM RH <i>new</i>	355.90	+
11	1 PC TAIL LAMP RH <i>Crackd</i>	375.90	+
12	1 PC TAIL LAMP PANEL RH <i>Repair</i>	297.90	+
13	1 PC TAIL LAMP LH <i>new</i>	375.90	+
14	1 PC REAR BUMPER <i>Dented</i>	492.20	✓
15	1 PC REAR BUMPER REINFORCEMENT <i>Dented</i>	316.10	✓
16	2 PCS REAR BUMPER SMALL RETAINERS <i>new</i>	145.40	+
17	2 PCS REAR BUMPER SIDE RETAINERS <i>new</i>	227.80	+
18	1 PC REAR REFLECTOR - RH <i>Crackd</i>	179.80	✓
		5,055.10	
Less 25%		1,263.78	3,791.37
Special Net			
19	1 PC BOOT LID 502 STICKER <i>new</i>	35.00	✓
20	1 SET REAR PANEL TRIM CLIPS <i>new</i>	30.00	20
21	1 SET REAR FENDER INNER TRIM CLIPS RH <i>new</i>	40.00	+
22	1 PC REAR FENDER STICKER RH <i>new</i>	290.00	+
23	1 SET REAR BUMPER CLIPS <i>new</i>	40.00	30
24	2 PCS REAR "L" PLATE BRACKETS <i>new</i>	70.00	30
25	1 PC "L" PLATE <i>Best</i>	50.00	✓

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : QBE INSURANCE (SINGAPORE) PTE LTD
1 RAFFLES QUAY
#29-10 SOUTH TOWER
SINGAPORE 048583
TEL: 62246633 FAX: 65345356
ATTN: Motor Claim Department

Estimate No: EST2100191

Date: 16 Jul 2021

Veh Reg No: SKR2843X

Make/Model: TOYOTA VIOS J GRADE MT

Chasis No: MHFBT9F3306029824

Reg. Date: 29/01/2015

Your Ref No: SLK6599A

Claim Type: Third Party
Accident Date: 15/07/2021
TP Veh Reg No: SLK6599A

Estimate Repair Cost to Vehicle No :SKR2843X

Quantity	Description	List Price	Amount
		SS	SS
26	1 SET REAR BUMPER STICKER <i>new</i> <i>495</i>	280.00 ✓	
	Rear Number Plate <i>sent.</i>	835.00	835.00
	Labour		
27	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00 <i>900</i>	
28	1 TO SPRAY PAINTING	1,000.00 <i>900</i>	
29	1 TO SPRAY UNDERSEAL	100.00 <i>80</i>	
30	1 TO REPLACE INNER TRIM	100.00 <i>80</i>	
31	1 TO CHECK WIRING	50.00 <i>30</i>	
32	1 TO REPLACE STICKERS	80.00 <i>x</i>	
		2,330.00	2,330.00
	Total		S\$ 6,956.37
	Add GST @ 7%		486.95
	Total Amount Payable		S\$ 7,443.32

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND FOUR HUNDRED FORTY THREE AND CENTS THIRTY TWO ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

Adnan Lj
L/S 19/07/21
06 Prys

total 5243.87
L/S: 42K