

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

21-Jul-21

Our ref : TP/5008/21

TP chine.
Asher.

Raghbir Singh S/o Darshan Singh

RE : Estimate cost for vehicle no : SLE 1746G

1 pc	rear bumper	Replaced	\$	586.50	✓
2 pcs	rear bumper lh retainer	LH M		240.00	65
1 pc	rear bumper lh reflector	new		65.00	+
4 pcs	rear bumper clips	new		20.00	✓
1 pc	end panel	Replaced		690.00	+
1 pc	rear bumper reinforcement	Dented		395.00	✓
1 pc	logo emblem			60.00	✓
1 pc	Corolla emblem	new	1611.50	45.00	✓
1 pc	Altis emblem			45.00	✓
1 pc	lh taillamp	Cracked	1208.62	395.00	✓
1 pc	bootlid lh reflector	new		355.00	+
				2,896.50	
less 25%				724.13	
				2,172.38	
1 pc	reverse sensor	Replaced	200	250.00	sniff 200
Panel beating.				600.00	400
Spray panting.			1030	800.00	600
Wiring.				30.00	✓
				3,852.38	
Plus 7% GST				269.67	
				4,122.04	

SD : four thousand one hundred twenty-two & cents four only.

Adrian L.
1/s 21/07/21
04 Days

total: 243862
1/s: 1.91c.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: