

Kg


Not Notified  
6/1/93 @ 4:20 PM  
Preserving After Paint

6 days

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Make/Model: TOYOTA COROLLA ALTIS  
Engine/Chassis No.: MR053ZEE106166646  
Date of accident:  
Damaged area: Rear

Date: 26/07/2021  
Claim Type: TP  
VRN: SMA8906A



| List items |                                  |     |            |             |
|------------|----------------------------------|-----|------------|-------------|
| S/N        | Parts description                | QTY | UNIT PRICE | AMOUNT      |
| 1          | Bootlid                          | 1   | \$ 813.00  | \$ 813.00   |
| 2          | Bootlid inner trim               | 1   | \$ 181.00  | \$ 181.00   |
| 3          | Bootlid hinge                    | 2   | \$ 67.00   | \$ 134.00   |
| 4          | Bootlid lock                     | 1   | \$ 159.00  | \$ 159.00   |
| 5          | Bootlid lock striker             | 1   | \$ 65.00   | \$ 65.00    |
| 6          | Bootlid key cylinder             | 1   | \$ 194.00  | \$ 194.00   |
| 7          | Bootlid release cable            | 1   | \$ 53.00   | \$ 53.00    |
| 8          | Bootlid weatherstrip             | 1   | \$ 185.00  | \$ 185.00   |
| 9          | Licence plate lamp               | 2   | \$ 72.00   | \$ 144.00   |
| 10         | Bootlid chrome garnish           | 1   | \$ 117.00  | \$ 117.00   |
| 11         | Bootlid hinge garnish            | 2   | \$ 49.00   | \$ 98.00    |
| 12         | Bootlid "TOYOTA" logo            | 1   | \$ 61.00   | \$ 61.00    |
| 13         | Bootlid lamp                     | 2   | \$ 474.00  | \$ 948.00   |
| 14         | Bootlid lamp sponge seal         | 2   | \$ 8.00    | \$ 16.00    |
| 15         | Rear bumper reflector            | 2   | \$ 66.00   | \$ 132.00   |
| 16         | End panel bumper support bracket | 2   | \$ 98.00   | \$ 196.00   |
| 17         | Rear bumper                      | 1   | \$ 688.00  | \$ 688.00   |
| 18         | Rear bumper side retainer        | 2   | \$ 57.00   | \$ 114.00   |
| 19         | Rear bumper sponge               | 1   | \$ 176.00  | \$ 176.00   |
| 20         | Rear bumper inner beam           | 1   | \$ 188.00  | \$ 188.00   |
| 21         | Taillamp                         | 2   | \$ 689.00  | \$ 1,378.00 |
| 22         | Taillamp sponge seal             | 2   | \$ 8.00    | \$ 16.00    |
| 23         | Taillamp panel                   | 2   | \$ 147.00  | \$ 294.00   |
| 24         | Taillamp lower bracket           | 2   | \$ 33.00   | \$ 66.00    |
| 25         | End panel                        | 1   | \$ 532.00  | \$ 532.00   |
| 26         | End panel top garnish            | 1   | \$ 164.00  | \$ 164.00   |
| 27         | Spare tyre floor panel           | 1   | \$ 795.00  | \$ 795.00   |
| 28         | Spare tyre top board             | 1   | \$ 127.00  | \$ 127.00   |
| 29         | Spare tyre                       | 1   | \$ 350.00  | \$ 350.00   |
| 30         | Rear fender n/s                  | 1   | \$ 798.00  | \$ 798.00   |
| 31         | Rear fender inner trim n/s       | 1   | \$ 155.00  | \$ 155.00   |
| 32         | Rear fender cowling n/s          | 1   | \$ 174.00  | \$ 174.00   |

# Repair Estimate

|               |                                |           |   |           |                     |   |
|---------------|--------------------------------|-----------|---|-----------|---------------------|---|
| 33            | Rear fender air duct n/s       | <i>sn</i> | 1 | \$ 87.00  | \$ 87.00            | X |
| 34            | Rear windscreen glass moulding | <i>nn</i> | 1 | \$ 177.00 | \$ 177.00           | X |
| 35            | Rear bumper top bracket        | <i>R</i>  | 4 | \$ 62.00  | \$ 248.00           | X |
| 36            | Rear fender inner panel        | <i>R</i>  | 2 | \$ 514.00 | \$ 1,028.00         | X |
| 37            | Spare tyre holder lock         | <i>R</i>  | 1 | \$ 79.00  | \$ 79.00            | X |
| 38            | Rear bumper splash guard       | <i>sn</i> | 2 | \$ 87.00  | \$ 174.00           | X |
|               |                                |           |   |           | <b>\$ 11,304.00</b> |   |
| List discount |                                |           |   |           | 25.00%              |   |
| Total         |                                |           |   |           | <b>\$ 8,478.00</b>  |   |

## Special nett items

| No.   | Parts description               | QTY          | UNIT PRICE | AMOUNT             |       |
|-------|---------------------------------|--------------|------------|--------------------|-------|
| 1     | Rear licence plate & frame      | <i>sn</i> 1  | \$ 55.00   | \$ 55.00           | X     |
| 2     | Reverse camera                  | <i>sn</i> 1  | \$ 450.00  | \$ 450.00          | X     |
| 3     | Reverse sensor                  | <i>sn</i> 1  | \$ 280.00  | \$ 280.00          | 2005m |
| 4     | Bootlid inner trim clips        | <i>nn</i> 10 | \$ 4.50    | \$ 45.00           | —     |
| 5     | Rear bumper clips               | <i>nn</i> 10 | \$ 4.50    | \$ 45.00           | —     |
| 6     | Taillamp clips                  | <i>nn</i> 6  | \$ 4.50    | \$ 27.00           | X     |
| 7     | Bootlid lamp clips              | <i>nn</i> 6  | \$ 4.50    | \$ 27.00           | X     |
| 8     | End panel sealant               | <i>nn</i> 1  | \$ 120.00  | \$ 120.00          | 301m  |
| 9     | End panel top garnish clips     | <i>nn</i> 6  | \$ 4.50    | \$ 27.00           | —     |
| 10    | Spare tyre floor panel sealant  | <i>nn</i> 1  | \$ 120.00  | \$ 120.00          | X     |
| 11    | Rear fender inner panel sealant | <i>nn</i> 1  | \$ 100.00  | \$ 100.00          | X     |
| 12    | Rear fender inner trim clips    | <i>nn</i> 8  | \$ 4.50    | \$ 36.00           | X     |
| 13    | Rear fender cowling clips       | <i>nn</i> 6  | \$ 4.50    | \$ 27.00           | X     |
| 14    | Rear windscreen glass sealant   | <i>nn</i> 1  | \$ 120.00  | \$ 120.00          | X     |
| 15    | Sundries                        | <i>nn</i> 1  | \$ 50.00   | \$ 50.00           | X     |
| Total |                                 |              |            | <b>\$ 1,529.00</b> |       |

## Labour

| No.          | Description                                                                                                                                 | Work unit | Amount             |      |
|--------------|---------------------------------------------------------------------------------------------------------------------------------------------|-----------|--------------------|------|
| 1            | To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.          | 6         | \$ 1,200.00        | 700f |
| 2            | To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings. | 0.25      | \$ 50.00           | 20f  |
| 3            | To remove, refit bootlid components and replace bootlid, check and re-adjust close gap, alignment and water seepage.                        | 0.5       | \$ 100.00          | 50f  |
| 4            | Supply spray paint material and necessary items to respray affected area / panel.                                                           | 6         | \$ 1,200.00        | 900f |
| 5            | To remove and refit rear windscreen to facilitate repair work.                                                                              | 0.75      | \$ 150.00          | X    |
| 6            | To rust proof all affected portions after repair.                                                                                           | 0.5       | \$ 100.00          | 60f  |
| Total labour |                                                                                                                                             |           | <b>\$ 2,800.00</b> |      |

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate Grand Total \$ 12,807.00