



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : THIRD PARTYVehicle No. : SJQ2568HMake & Model : HYUNDAI AVANTEYear of Manufacture : 2009Chassis No. : KMH DU41BR9U750072Ins Company : AIG vs MS FCIEngine No. : G4FC9U647492

Excess : _____

Policy No. : 2100133918Date of Accident : 20/07/2021Time of Accident : 1602

Suggested Days of Repair : _____

In-house Vehicle Assessor**Repair Estimates**Case Owner : BRENDA

Signature : _____

Parts (a) Cost / List Price Items \$ 2,214.00Plus/Less 20% \$ 442.80Total of Cost / List \$ 1,771.20(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 1,771.20Labour (Appendix B) \$ 1,230.00Total Repair Cost \$ 3,001.20

Contact No

Frt Counter Operation

63837103 - Patrick Tia

PatrickTia@sparkcarcare.com

63837730 - Brenda Ng

BrendaNg@sparkcarcare.com

63837466 - Rohani

RohaniM@sparkcarcare.com**Workshop Operation**

63837656 - Ngo Toh Wee

Ngotw@sparkcarcare.com

63838115 -

63837362 -

The above total will be subjected to 7% G.S.T.

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SJQ2568H Case Owner : BRENDA

Make & Model : HYUNDAI AVANTE Year Manufacture : _____

Chassis No : KMH DU41BR9U750072 Engine No : G4FC9U647492

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : THIRD PARTY

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR RH DOOR HANDLE	1		\$ 48.00			
2	REAR RH DOOR HANDLE SIDE COVER	1		\$ 20.00			
3	REAR RH DOOR HANDLE INNER BACK BASE	1		\$ 43.00			
4	REAR RH DOOR	1		\$ 1,744.00			
5	REAR RH DOOR BLACK STICKER	1		\$ 45.00			
6	REAR RH DOOR GLASS OUTER MOULDING	1		\$ 46.00			
7	REAR RH DOOR LOCK	1		\$ 268.00			
8	0	1					
9	0	1					
10	0	1					
11	0	1					
12	0	1					
13	0	1					
14	0	1					
15	0	1					
16	0	1					
17	0	1					
18	0	1					
19	0	1					
20	0	1					
21	0	1					
22	0	1					
23	0	2					
24	0	1					
25	0	1					
26	0	1					
27	0	1					
28	0	1					
29	0	1					
30	0	1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No.	: <u>SJQ2568H</u>	Case Owner	: <u>BRENDA</u>
Make & Model	: <u>HYUNDAI AVANTE</u>	Year of Manufacture	: <u>2009</u>

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.