



AUTOMOTIVE GROUP

Our Ref : OD/072021/4906
Accident date : 16/7/2021
Your Ref : MPC21P00057700

MOTOR CLAIM DEPARTMENT
ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987
Tel : 6337 4779/ 6303 0167

ESTIMATE COST OF REPAIRS TO

Vehicle No : SLX3308A
Model : MERCEDS BENZ / C180 AVANTGRADE (R17 LED)

1	pc	Front RH headlamp (Order) / CFA	\$	1,800.00
1	pc	Front grille base - BR	\$	70.00
1	pc	Front grille housing - BR	\$	70.00
1	pc	Front grille emblem - cut	\$	70.00
1	pc	Front bumper - BR	\$	880.00
2	pcs	Front bumper parking sensor @ \$100.00 ?	\$	200.00
1	pc	Front bumper no.plate garnish - CFA	\$	70.00
1	pc	Front bumper centre lower grille X	\$	70.00
1	pc	Front bumper RH side retainer X	\$	50.00
1	pc	Front bumper LH side retainer X	\$	50.00
1	pc	Front bumper sponge - CFA	\$	90.00
1	pc	Front bumper reinforcement - BT	\$	270.00
1	pc	Front bumper air duct - BR	\$	30.00
1	pc	Front bumper top beam - CFA.	\$	50.00
10	pcs	Front bumper clips @ \$4.00 - rec.	\$	40.00

Grille chrome x4 - cut
Add 10%

UH Headlamp - CFA.

1 pc Front no.plate - CFA \$ 40.00 N

To reset front headlamp
To repair front damage
To spray painting

\$ 280.00 150
\$ 480.00 320
\$ 380.00 20.
\$ 5,371.00

VIN'S MOTOR PTE LTD

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Tax Invoice

Date :

KK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Excess - TBA
Not Authorized
23/7/2021
3 Days.

Geno Rial
8288082
P/P. Refal part photo S.