

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM21007873/T1qce2 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 29/07/2021 SINGAPORE 068811 ATTN: CHAN KIAN CHUAN Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SHC 7039H** FBR 5835G Veh. Inspected Policy No. VFX/P2419140 Coverage (\$) 0.00 Claim No. S1M03DAM Excess (\$) 0.00 **CHAN KIAN CHUAN Assign Date** 23/07/2021 Assign From **Vehicle Particulars & Condition** 2. YAMAHA AEROX c.c 155 Make & Model HIDDEN 2020 Engine No. Year of Reg. MH3SG4640LJ069756 RED Chassis No. Colour Odometer Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 110/80 R17 PIRELLI 5 mm L/H Front Tyre mm 150/70 R14 **PIRELLI** R/H Rear Tyre 5 mm L/H Rear Tyre mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION. 5. **General Information** 06/07/2021 23/07/2021 (05:00 PM) Inspect Date / Time Accident Date WILL MOTOR TRADING & CREDIT PTE LTD Survey held at BLK 3012 BEDOK INDUSRTIAL PARK E #01-2076 SINGAPORE 489978 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500-\$5,500 5b. **Estimate Days of Repair ESTIMATED NORMAL PERIOD FOR REPAIR:** 7 Working Days

Report Ref No. CS3/ASM21007873/T1qce2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.