



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI21007875/Gvc	
			Date: 23/07/2021	
			Code: CTI	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SGZ 1414M	Veh. Inspected	SLT 1088T	
Policy No.		Coverage (\$)	0.00	
Claim No.	SNM21D204038/C02/SGZ1414 M/TAYHP	Excess (\$)	0.00	
Assign From	IRENE TAY	Assign Date	23/07/2021	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	19/07/2021	Inspection Date	23/07/2021	
Survey held at	ECLIPSE AUTO PTE LTD 155 KAKI BUKIT AVENUE 1 #01-00 SHUN LI INDUSTRIAL PARK SINGAPORE 416012			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				