



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2104849

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 09/07/2021
Reference CC6/III21004512/Ags3q2
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SJN 393Z Bill cancel refer to new invoice No. AC2106990 08/10/2021 \$611.00
Insured Veh. XE 1098B
Claim No. MFL2021D0001579
Policy No. D20MFL0004151
Accident Date 06/04/2021
Inspection Date 07/04/2021

Description	Total
Survey Inspection	450.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Merimen Fee	11.00
Subtotal	461.00
GST (7%)	32.27
Grand Total	493.27

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2106990

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 08/10/2021
Reference CC6/III21004512/Ags3q2-1
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SJN 393Z
Insured Veh. XE 1098B
Claim No. MFL2021D0001579
Policy No. D20MFL0004151
Accident Date 06/04/2021
Inspection Date 07/04/2021

Description	Total
Survey Inspection	600.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Merimen Fee	11.00
Note: Pls discard Inv.AC2104849 dated 09/07/2021 \$493.27	
Subtotal	611.00
GST (7%)	42.77
Grand Total	653.77

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM