

ASS. REC. BY:

Tanjim 1 CC4 / AIG 21007887 / T. 093

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$14k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: Daniel

Veh No: FBS5531C

Yr Regn: 2021 / May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha MTN155

c.c. 155

Colour: Grey / White

A/C: Insured / Std / NI / NA

Sp. Reading: 632

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MH3RG71100000

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/70R17

R: 140/70R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Winner

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. mm

L/Bal. mm

D.O.A. _____

D.O.I. 23/7/21 0330pm

Survey held at Yamaha Division

Des. of Damages: Frt / Rear / O/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Rep. Format:

Lump Sum / L.B. ()

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

Hong Leong Corporation Holdings Pte Ltd

Yamaha Division (Incorporated in Singapore)

178 Paya Lebar Road #01-01, Singapore 409030
Tel: 6746 0415 / 6749 0588 / Fax: 6748 9238 / 6748 9238

22/7/2021

AIG Building
78 Shenton Way, Level 1
Singapore 079120

Attention: Vehicle Claim Department

Dear Sir / Mdm,

ESTIMATED COST OF ACCIDENT REPAIR FOR YAMAHA MOTORCYCLE MODEL MTN155 OF REGISTRATION NO. FBS5531C

The above-captioned motorcycle is currently in our workshop.

Our client, rider of Yamaha motorcycle with registration no. FBS5531C is doing a 3rd party claim against your client driver of SLM2723Z.

We append herewith the estimated quotation for the repair/replacement of the damaged parts

S/no	Description	Qty	Unit Price	Total Price
DISCOUNT ITEMS				
1	MUFFLER COMP 1	1	\$ 210.00	\$ 210.00
2	PROTECTOR, MUFFLER	1	\$ 22.00	\$ 22.00
3	GUARD, MUD	1	\$ 5.00	\$ 5.00
4	FRONT FORK ASSY	1	\$ 635.00	\$ 635.00
5	CALIPER ASSY (RHS)	1	\$ 70.00	\$ 70.00
6	HANDLEBAR	1	\$ 25.00	\$ 25.00
7	STOPPER	2	\$ 3.00	\$ 6.00
8	END GRIP	2	\$ 6.00	\$ 12.00
9	BOLT, HEX, SOCKET HEAD	2	\$ 2.50	\$ 5.00
10	WASHER, PLATE	2	\$ 1.50	\$ 3.00
11	PEDAL, BRAKE	1	\$ 28.00	\$ 28.00
12	COVER, SHIFT PEDAL	1	\$ 1.50	\$ 1.50
13	PIN, COTTER	2	\$ 2.00	\$ 4.00
14	BRACKET 4	1	\$ 14.00	\$ 14.00
15	LEVER 1	1	\$ 8.00	\$ 8.00
16	SHIFT PEDAL ASSY	1	\$ 20.00	\$ 20.00
17	REAR VIEW MIRROR (LHS)	1	\$ 7.00	\$ 7.00
18	REAR VIEW MIRROR (RHS)	1	\$ 7.00	\$ 7.00
19	CAP	1	\$ 30.00	\$ 30.00
Sub Total				\$ 1,112.50
Discount: Less 10%				\$ 111.25
Sub Total (A)				\$ 1,001.25
NETT ITEMS				
1	TOWING - 2 WAY	1	\$ 80.00	\$ 80.00
2	RACK	1	\$ 100.00	\$ 100.00
3	FORK OIL	1	\$ 20.00	\$ 20.00
4	LABOUR - ADJUST ALIGNMENT	1	\$ 120.00	\$ 120.00
4	BRAKE FLUID	1	\$ 20.00	\$ 20.00
5	REAR NUMBER PLATE	1	\$ 28.00	\$ 28.00
6	LTA - VEHICLE INSURANCE ENQUIRY	1	\$ 7.00	\$ 7.00
7	LABOUR - REPLACE ACCIDENT PARTS	1	\$ 720.00	\$ 720.00
Sub Total (B)				\$ 1,095.00
Total (A) + (B)				\$ 2,096.25

* Price is subject to 7% GST Upon Invoicing.

Kindly assign a Surveyor down to our Workshop as soon as possible.

In the meantime, please do not hesitate to contact me at TEL: 6746 0415 (ext 122) should you have further clarifications to the said matter.

Thank you.

Yours sincerely

Danial Zhang

Hong Leong Corporation Holdings Pte Ltd
YAMAHA DIVISION

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: _____

Taufik 97495749/62563561
J-WP' 23/7/21 @ 330pm
* Resurvey new parts 4DAYS
taufik@lkkauto.com