

Hong Leong Corporation Holdings Pte Ltd

Yamaha Division (Incorporated in Singapore)

178 Paya Lebar Road #01-01, Singapore 409030
Tel: 6746 0415 / 6749 0588 / Fax: 6748 9238 / 6748 9238

22/7/2021

AIG Building
78 Shenton Way, Level 1
Singapore 079120

Tel: 64193000
Fax:

Email: claimsdocmanagement@aig.com

Attention: Vehicle Claim Department

Dear Sir / Mdm,

ESTIMATED COST OF ACCIDENT REPAIR FOR YAMAHA MOTORCYCLE MODEL MTN155 OF REGISTRATION NO. FBS5531C

The above-captioned motorcycle is currently in our workshop.

Our client, rider of Yamaha motorcycle with registration no. FBS5531C is doing a 3rd party claim against your client driver of SLM2723Z

We append herewith the estimated quotation for the repair/replacement of the damaged parts

S/no	Description	Qty	Unit Price	Total Price
DISCOUNT ITEMS				
1	MUFFLER COMP 1	1	\$ 210.00	\$ 210.00
2	PROTECTOR, MUFFLER	1	\$ 22.00	\$ 22.00
3	GUARD, MUD	1	\$ 5.00	\$ 5.00
4	FRONT FORK ASSY	1	\$ 635.00	\$ 635.00
5	CALIPER ASSY (RHS)	1	\$ 70.00	\$ 70.00
6	HANDLEBAR	1	\$ 25.00	\$ 25.00
7	STOPPER	2	\$ 3.00	\$ 6.00
8	END GRIP	2	\$ 6.00	\$ 12.00
9	BOLT, HEX, SOCKET HEAD	2	\$ 2.50	\$ 5.00
10	WASHER, PLATE	2	\$ 1.50	\$ 3.00
11	PEDAL, BRAKE	1	\$ 28.00	\$ 28.00
12	COVER, SHIFT PEDAL	1	\$ 1.50	\$ 1.50
13	PIN, COTTER	2	\$ 2.00	\$ 4.00
14	BRACKET 4	1	\$ 14.00	\$ 14.00
15	LEVER 1	1	\$ 8.00	\$ 8.00
16	SHIFT PEDAL ASSY	1	\$ 20.00	\$ 20.00
17	REAR VIEW MIRROR (LHS)	1	\$ 7.00	\$ 7.00
18	REAR VIEW MIRROR (RHS)	1	\$ 7.00	\$ 7.00
19	CAP	1	\$ 30.00	\$ 30.00
	Sub Total			\$ 1,112.50
	Discount: Less 10%			\$ 111.25
	Sub Total (A)			\$ 1,001.25
NETT ITEMS				
1	TOWING - 2 WAY	1	\$ 80.00	\$ 80.00
2	RACK	1	\$ 100.00	\$ 100.00
3	FORK OIL	1	\$ 20.00	\$ 20.00
4	LABOUR - ADJUST ALIGNMENT	1	\$ 120.00	\$ 120.00
4	BRAKE FLUID	1	\$ 20.00	\$ 20.00
5	REAR NUMBER PLATE	1	\$ 28.00	\$ 28.00
6	LTA - VEHICLE INSURANCE ENQUIRY	1	\$ 7.00	\$ 7.00
7	LABOUR - REPLACE ACCIDENT PARTS	1	\$ 720.00	\$ 720.00
	Sub Total (B)			\$ 1,095.00
	Total (A) + (B)			\$ 2,096.25

** Price is subject to 7% GST Upon Invoicing.*

Kindly assign a Surveyor down to our Workshop as soon as possible.

In the meantime, please do not hesitate to contact me at TEL: 6746 0415 (ext 122) should you have further clarifications to the said matter.

Thank you.

Yours sincerely

Danial Zhang

Hong Leong Corporation Holdings Pte Ltd
YAMAHA DIVISION