

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIG21007889/AQF3N2**Date:** 18/11/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100482779
Claimant Vehicle No :	GZ4436E	Insured Vehicle No :	SLF9360C
Date of Loss:	23/07/2021	Nature of Claim:	TP
		Claim No:	4576151042SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GZ4436E	Engine No:	QD32221540
Make & Model:	NISSAN CABSTAR G, 3.2 D (M)	Chassis No:	JN1SF4F23Z0861009
Reg. Date:	22/04/2006 (Man. Year: 2006)	Odometer:	309025 km
Colour:	Gold		
Engine Capacity:	3153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195R15C	Rear Tyre Size:	155R12C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	GREEN-MAX 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	GREEN-MAX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,256.84	3,096.84	2,160.00	41.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,270.00	1,360.00	910.00	40.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,526.84	4,456.84	3,070.00	40.79
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	7,526.84	3,500.00	4,026.84	53.50

INSPECTION

Date of Assignment:	23/07/2021	Unimotor Company - Kaki Bukit (HQ) 1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) Singapore 417883
Date Inspected:	27/07/2021 Inspected At:	
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE ASSY	Dented	1,878.40 FN	*1,399.70 FN
2	3		*REAR TAILGATE HINGES	Not Necessary	338.40 FN	*- FN
3	2		*REAR SIDE PANEL	Repair	524.60 FN	*- FN
4	1		*REAR END PANEL	Dented	687.60 FN	*425.00 FN
5	2		*REAR COMBINATION LAMP ASSY	Cracked	618.80 FN	*450.00 FN
6	2		*REAR COMBINATION LAMP BRACKET	Bent	222.60 FN	*222.60 FN
7	1		*REAR TAILGATE SIDE LOCK HINGES	O/s Dented	247.20 FN	*123.60 FN
8	1		*REAR TAILGATE RUBBER STOPPER	N/s Missing	36.60 FN	*18.30 FN
9	1		*REAR TAILGATE NISSAN STICKER	Necessary	198.60 FN	*142.00 FN
10	2		*REAR NUMBER PLATE LAMP	Not Necessary	128.40 FN	*- FN
11	1		*REAR NUMBER PLATE BRACKET	Bent	176.40 FN	*176.40 FN
12	1		*REAR NUMBER PLATE	Bent	25.00 FS	*25.00 FS
13	1		*REAR TAILGATE (8 PAX) STICKER	Necessary	15.00 FS	*15.00 FS
14	1		*REAR TAILGATE (70KM/H) STICKER	Necessary	15.00 FS	*15.00 FS
15	1		*REAR REVERSE SENSOR	Damaged	300.00 FS	*200.00 FS
16	1		*REAR ALUMINUM PLATE (TAILGATE)	Bent	350.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	5,762.60	3,392.60
- Nett Item Discount on N Items 10.00/10.00% (S\$)	505.76	295.76
Total Parts (S\$)	5,256.84	3,096.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISM/REWIRE DAMAGED PORTION	New	120.00	80.00
2	TO PANEL BEAT DAMAGED PORTION AND RENEW REAR TAILGATE,REAR FLOOR PANEL	New	1,000.00	600.00
3	TO RENEW REAR ALUMINUM PLATE	New	100.00	30.00
4	TO RENEW REAR TAILGATE EMBLEM STICKER	New	50.00	0.00
5	TO PUTTY AND RESPRAY DAMAGED PORTION	New	850.00	600.00
6	TO SPRAY UNDERCOATING IN REPAIR	New	150.00	50.00
Gross Labour Cost (\$)			2,270.00	1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >