

A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113
HP: 8386 8989 Email: atautoconsultant@gmail.com
Co. Reg. No. : 53368526E

Not Authorized
11 Amp \$9050/hr
Repair After Paint
8 days

Date of Estimate: 28.07.2021
Vehicle No: SJY9825C
Owner: ONG AH KIM
Date of Accident: 23.07.2021
Make & Model: Toyota Wish
Chassis No : JTDGJ20W805003212

ESTIMATE FOR ACCIDENT VEHICLE NO SJY9825C

PARTS

1	1 Front bumper
2	2 Front bumper side retainer
3	1 Front bumper lower grille RH
4	1 Front bumper fog lamp cover RH
5	1 Radiator lower cover
6	2 Head lamp RH/LH <i>0672</i>
7	1 Wiper tank
8	2 Front fender RH/LH <i>0786.90</i>
9	1 Front fender inner garnish LH
10	2 Front wheel arch garnish RH/LH
11	1 Front wheel inner garnish LH
12	1 Front pillar outer LH
13	1 Front wheel hub panel LH (repair)
14	1 Bonnet (repair)
15	1 Front door LH (repair)
16	1 Rocker panel garnish LH
17	1 Front support panel
18	1 Cross member center <i>1454.20</i>
19	1 Cross member front
20	1 Engine mounting front
21	1 Engine mounting rear
22	1 Steering rack
23	1 Tie rod end LH
24	1 Stabilizer bar <i>328</i>
25	1 Stabilizer bar linkage LH
26	1 Driver shaft <i>1258.70</i>
27	1 Absorber LH
28	1 Absorber mounting LH
29	1 Absorber coil spring LH
30	1 Lower arm LH
31	1 Lower arm ball joint LH
32	1 Kunckle arm LH
33	1 Wheel hub LH
34	1 Disc rotor LH
35	1 Brake pad LH

Buc/cm	\$532.00	✓
nl/cm	\$61.00	\$121.00 ✓
sl	\$51.00	X
sl	\$95.00	X
cm	\$186.00	✓
@ ol/cm	nl/20	\$993.00
		\$1,986.00 ✓
@ ol/r	nl/21	\$889.00
		\$1,778.00 ✓
@	nl/cm	\$186.00
		\$372.00 ✓
	Replaced	\$165.00 X
	R	\$698.00 X
		\$0.00
		\$0.00
		\$0.00
Return/cm	\$506.00	✓
R	\$1,365.00	X
Bt	\$1,860.00	✓
R	\$465.00	X
DI	\$168.00	✓
DI/cm	\$221.00	✓
Bt/cm	\$1,623.00	✓
Bt	\$145.00	✓
Bt	\$428.00	✓
DI	\$213.00	✓
Bt	\$1,425.00	✓
Bt	\$412.00	✓
Bt	\$210.00	✓
sl	\$450.00	X
Bt	\$452.00	✓
Bt	\$195.00	✓
Bt	\$427.00	✓
Bt	\$235.00	✓
sl	\$366.00	X
sl	\$145.00	X

SUB TOTAL

LESS 25 %

DISCOUNTED SUB TOTAL

Page 1 of 2

\$17,665.00

\$4,416.25

\$13,248.75