SPECIAL N	ETT ITE			1.0	\$420.00	250 \$640.00 nc \$240.00	5605a
1	1	Front sport Rim RH/LH	@	alspin	\$320.00	250 \$640.00	LY2001
2	1	Front Tyre 205/55/R16 RH/LH	@	80112	\$30.00	NE \$240.00	Som
3	8	Gear box transmission fluid X 8L	@		\$30.00	\$1,720.00	
			SUB TOTAL				
			LESS 0 %			\$0.00	
			DISCOUNTED SUB	TOTAL		\$1,720.00	
1 2 3	Panel beating for replace and repair affected parts Spray painting on accident areas Wiring charges Remove/refix undercarridge				\$1,500.00 Fool \$1,500.00 Sool \$80.00 20l \$500.00 320 \$300.00 30l		
4 5							
		Apply undercoating to above affected areas			\$180.00 601		
6		eel alignment				~~ \$150.00	
7		ove/refix front quarter glass				~~ \$300.00	E Charac
8	Re-a	lignment of front member				\$4,510.00	- / -
			SUB TOTAL (LABO	OUR)		\$4,510.00	=

PLEASE NOTE THAT THE ABOVE IS ONLY AN ESTIMATE. THEREFORE, SHOULD THERE BE ANY ADDITIONAL PARTS REQUIRE OR DISCOVER DAMAGE DURING OUR COURSE OF REPAIRS, WE WOULD INFORM YOU ACCORDINGLY FOR NECESSARY ACTION. PRICES OF PARTS QUOTED ARE SUBJECT TO CHANGE WITHOUT NOTICE.

APPROVING OFFICER SIGNATURE & COMPANY'S CHOP

LKK Auto Consultants hence notify

the Repairer of the following:

To resurvey before after spray painting

To display damaged part(s) during resurvey

- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: