

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC3/AIG21007907/KPA3Q2

Date:

14/09/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

0999993578

Claimant Vehicle No : SHD5985J**Insured Vehicle No :**

SMP2672J

Date of Loss: 21/07/2021

Nature of Claim:

TP

Claim No:

2210397231SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHD5985J**

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)

Engine No: 2ZR2B76398

Reg. Date: 22/11/2018 (Man. Year: 2018)

Chassis No: JTDKB3FU803076966

Colour: Metallic Pearl White/Red

Odometer: 369467 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Sailun 9 mm

Rear Left Side: Sailun 8 mm

Front Right Side: Sailun 9 mm

Rear Right Side: Sailun 8 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,663.37	1,075.25	1,588.12	59.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,790.00	430.00	4,360.00	91.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,453.37	1,505.25	5,948.12	79.80
+ GST 7.00/7.00% (S\$)	521.74	105.37	416.37	79.80

Nett Amount (S\$)	7,975.11	1,610.62	6,364.49	79.80
<hr/>				
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$112.35/day) (S\$)		337.05		
+ Doc/Search Fee (S\$)		7.45		
		<hr/>		
Nett Liability (S\$)		2,105.12		
		<hr/>		
Global Sum Settlement (S\$)		2,100.00		
		<hr/>		

INSPECTION

Date of Assignment: 23/07/2021

Date Inspected: 23/07/2021

Estimated Period of Repair: 2.0 days

Inspected At: Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LENS AND BODY ,REAR LAMP ,RH	Serviceable	502.00 FL	*- FL
2	1		*LENS & BODY ,REAR COMBINATION LAMP ,RH	Serviceable	451.80 FL	*- FL
3	1		*COVER ,REAR BUMPER	Buckled / Dented	442.60 FL	*442.60 FL
4	1		*COVER ,REAR BUMPER ,LOWER	Dented	15.40 FL	*15.40 FL
5	1		*FILLER ,REAR BUMPER EXTENSION ,RH	Serviceable	123.70 FL	*- FL
6	1		*GUARD ,REAR BUMPER ,CENTER	Dented	576.30 FL	*576.30 FL
7	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Dented	332.70 FL	*332.70 FL
8	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
9	1		*REAR BUMPER CLIP	Necessary	65.00 FS	*50.00 FS
10	1		*REAR TAIL LAMP CLIP	Not Necessary	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,274.50	1,417.00
- List Item Discount on L Items 25.00/25.00% (\$)	611.13	341.75
Total Parts (\$)	2,663.37	1,075.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	0.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	220.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
5	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,800.00	200.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (S\$)			4,790.00	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >