Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5985J

AAD2107-057

Not Norhaite Permy B& paint

Vehicle No.: SHD5985J			
Chassis No.: JTDKB3FU803076966			
Vehicle Make: 23 JUL 2021 TOYOTA			
Vehicle Model: PRIUS			
Date of Accident:			
Third Party Insurer:			
Date of Registration: 22/11/2018			
PART			
1 LENS AND BODY, REAR LAMP, RH \$ 502.00	X		
1 LENS & BODY, REAR COMBINATION LAMP RH	×		
1 COVER, REAR BUMPER \$ Bullet 442.60	_		
1 COVER, REAR BUMPER, LOWER \$ 15.40			
1 FILLER, REAR BUMPER EXTENSION, RH \$ 123.70			
1 GUARD, REAR BUMPER, CENTER \$ 576.30			
1 REINFORCEMENT SUB-ASSY, REAR BUMPER \$ BT 332.70			
	•		
25% \$ 611.13			
\$ 1,833.38			
Charles Made			
Special Nett 1SET PARKING AID			
700.00	X		
1 REAR BUMPER CLIP \$ 65.00	501m		
1 REAR TAIL LAMP CLIP \$ 65.00	X		
TOTAL \$ 830.00			
TOTAL PARTS \$ 8,543.40	1		

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$ Nr 250.00 X
Putty And Spray Painting Of The Affected Portion.	\$ 1,800.00 2201
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$ 280.00 X
To Check Electrical Lighting Concerned.	\$ 170.00 10/

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD5985J

Panel Beating, Knocking And Straightening The Necessary		
Portion, Remove And Renewal Of Parts, Adjust And Realign The		
Same	\$ 1,800.00	2001
To check steering geometry and computer wheel alignment	\$ NN 220.00	X
To transfer of rear fender panel fittings, attachment and perform		
water seepage test.	\$ ~~ 170.00	X
TOTAL	\$ 4,790.00	'
Over All Total	\$ 15,166.78	- 1 PACE
		V., A., 18

(PART-BY-PART) Repair Days

Toyus

for Chi

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: